

One string of casing will have to be cemented from the top of the anhydrite to the surface or surface casing.

Any of the following is O. K.:

1. Set surface to top of anhydrite
2. Set D. V. tool in long string at top of anhydrite
3. Cement long string to surface