STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION					
SANTA FE					
FILE					
U.S.G.B.					
LAND OFFICE					
OPERATOR		l			

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISIC P. O. BOX 2088 SANTA FE, NEW MEXICO 87501

Fo	FR	C-1	103	•
	v 1 e	e A	10-	1 - 75

FILE	Sa. Indicate Type of Lease
U.S.G.B.	State X Fee
LAND OFFICE	5. State Oil & Gas Lease No.
OPERATOR	L-2775
DEPORTS AND DEPORTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUE BACK TO A DIFFERENT RESERVOIR. (DO NOT USE THIS FORM FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
	7. Unit Agreement Name
OIL 🔯 SAS DATUERS	
WELL [2] WELL DINE	B. Farm or Lease Name
2. Name of Operator	Land]ady
Bravo Operating Co.	9. Well No.
3. Address of Operator	1
P.O. Box 2160, Hobbs NM 88241	10. Field and Pool, or Wildcat
4. Location of Well 1080*	North Caprock Wolfcamp
UNIT LETTER B 660 PEET PROM THE NOTTH LINE AND 1980 PEET PROM	MITTERNITA
2 120 325	
THE EAST LINE, SECTION 8 TOWNSHIP 12S RANGE 32E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	Lea
GR 4403	
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	er Data
NOTICE OF INTENTION TO: SUBSEQUENT	REPORT OF:
	ALTERING CASING
PERFORM REMEDIAL WORK	=
TEMPORARILY ABANDON	PLUS AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CEMENT JOB	
DTHER	
07 HEA	•
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
work) NEE RULE 1103.	
n = 5 = 0(10 0(1 +1/50 ex coment	
1. Squeeze Perfs 8618-26 w/50 sx cement.	
o of the off 0 6210! & pull	
2. Shoot tubing off @ 6210' & pull.	
3. Shoot 5 1/2" csg off @ 6200' & pull.	
Displace hole with salt gel mud.	
pispiace note with said get muc.	
4. Set 50 sx plug @ 6200' to 6100' and tag plug.	
4. Set 30 Sx plug e 0200 to 0200 and and a	
5. Set 50 sx plug @ 5010' to 4910'.	
J. Bet Jo ax prag c boxe	
6. Set 50 sx plug @ 3750' to 3650' and tag plug.	et were be a som ty 🥳
7. Set 50 sx plug @ 1610' to 1510'.	
8. Set 10 sx plug @ surface.	
9. Install dryhole marker, clean location and ready for inspection.	
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	·
Vice President	August 10, 1988
SIGNED	
ORIGINAL SIGNED BY JERRY SEXTON	88'S 1 2UA
DISTRICT 1 SUPERVISOR VITLE	DATE