STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	<u> </u>		
DISTRIBUTION			
SANTA FE			
FILE			
U.S.G.S.			
LAND OFFICE			
OPERATOR	T		

CONDITIONS OF APPROVAL, IF ANY

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 Revised 10-1-78

Store	SANTA FE	SANTA FE, NEW MEXICO 87501	
S. She coil & Cose Leves No. Core not not a Cose Leves No. Sundry Notices AND REPORTS ON WELLS. Sundry Notices AND REPORTS ON WELLS. The second of Complete State State No. Second of Core No. Location of West No. 10. Field and Food, or Wideler 900 Neil P. Anderson Bldg., 411 W. Seventh St., Ft. Worth, TY 76102 Location of West West Line, section 31 ** No. 15. Field and Food, or Wideler 16. Field and Food, or Wideler West Line, section 31 ** No. 16. Field and Food, or Wideler West Line, section 31 ** No. 16. Field and Food, or Wideler West Line, section 31 ** No. 16. Field and Food, or Wideler Will deat West Line, section 31 ** No. 16. Field and Food, or Wideler Will deat Will deat Will deat Will deat Will deat Will deat ** West Line, section 31 ** No. 16. Field and Food, or Wideler Will deat Wil	U.S.G.S.		5a. Indicate Type of Lease
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS			
The proposed or Completed Operations (Clearly state all pertinent dentils, and give persinent dates, including extinated date of starting casp propose or take the person of the person	OPERATOR	•	
##ILL Dry Hole S. Furn of Letter Home Rel 1011, Inc. S. West No.	SUNDRY N ON NOT USE THIS FORM FOR PROPOSA USE "APPLICATION FOR	OTICES AND REPORTS ON WELLS	voir.
Note of Germany 900 Meil P. Anderson Bldg., 411 M. Seventh St., Ft. Worth, TX 76102 10. Fleid and Peol, or Wildean Wildcat West	OIL GAS	D H-1-	7. Unit Agreement Name
Note 1980 1 1980 1 1980 1 1980 1 1980 1 1980 1 1980 1 1980 1 1980 1 1980 1 1980 19		DTHER- DRY HOLE	1
900 Netil P. Anderson Bldg., 411 W. Seventh St., Ff. Worth, TX 75102 Location of Netil West	Kelloil, Inc.		
Lecation of Well West thet, steriou 31 township 11-S save 35-E where GR - 4140.1', DF - 4155', KB - 4156' Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ***********************************		da 111 W Seventh St. Et Worth T	1
West LINE, SECTION 31 TOWNSHIP 11-5 NAMEE 35-E WARD. 13. Cleveling (Show whether DF, RT, CR, etc.) 12. County	Location of Well		Wildest
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUE AND ABANDON Content of Notice	UNIT LETTER F 198	O FEET FROM THE NORTH LINE AND 1980	- FEET FROM
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ALTERING CASING FLUG AND ABANDON	THE West LINE, SECTION	31 TOWNSHIP 11-S RANGE 35-E	имрм.
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PLUE AND ABANDON	mmmmm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK COMMENCE OF INTENTION TO: ALTERIANG CASING ALTERIANG CASING PLUC AND ABANDOMMENT COMMENCE OF INTENTION TO: ALTERIANG CASING ALTERIANG CASING ALTERIANG CASING ALTERIANG CASING ALTERIANG CASING ALTERIANG CASING PLUC AND ABANDOMMENT COMMENCE OF INTENTION TO: ALTERIANG CASING ALTERIANG ALTERIANG ALTERIANG CASING ALTERIANG CASING ALTERIANG ALTERI			20
OTHER OTHER CASING CEMENT AND CEMENT AN	Check App		
COMMENCE PRINCIPLES CHANGE PLANS CHANGE PL	SPECIAL REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
OTHER Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE (163. Total Depth - 10,425' 13-3/8" casing at 400'; 8-1/8" casing at 4200'. Hole to be filled with 9.4#/gal. drilling mud. To spot cement plugs follows through drillpipe by Halliburton: 1.35 sacks from 10,275'-10,375' (Across top of Ranger Lake Zone)	i i	COMMENCE DRILLING OPN	S. PLUG AND ABANDONMENT
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103. Total Depth - 10,425' 13-3/8" casing at 400'; 8-1/8" casing at 4200'. Hole to be filled with 9.4#/gal. drilling mud. To spot cement plugs follows through drillpipe by Halliburton: 1. 35 sacks from 10,275'-10,375' (Across top of Ranger Lake Zone) 2. 35 sacks from 9945'-10,045' (Across top of Bo-A Zone) 3. 35 sacks from 7800'-7900' (Across top of Abo Zone) 4. 35 sacks from 7800'-7900' (Across top of Abo Zone) 4. 35 sacks from 4150'-4250' (Across base of 8-5/8" casing) 6. 35 sacks from 2150'-2250' (Across top of salt Zone) 7. 10 sacks in top of 8-5/8" & 13-3/8" casing at surface 8. 5 sacks in rat & mouse holes 9. Weld steel plate on top of surface casing. 10. Erect permanent marker on top of steel plate. Plugging operations to begin on November 30, 1979. Verbal approval of above program received from Mr. J. T. Sexton 11/3	ULL OR ALTER CASING		r aga [_]
Total Depth - 10,425'	OTHER		
13-3/8" casing at 400'; 8-1/8" casing at 4200'. Hole to be filled with 9.4#/gal. drilling mud. To spot cement plugs follows through drillpipe by Halliburton: 1. 35 sacks from 10,275'-10,375'(Across top of Ranger Lake Zone) 2. 35 sacks from 9945'-10,045'(Across top of Bo-A Zone) 3. 35 sacks from 7800'-7900'(Across top of Abo Zone) 4. 35 sacks from 5540'-5640')Across base of San Andres) 5. 35 sacks from 4150'-4250'(Across base of 8-5/8" casing) 6. 35 sacks from 2150'-2250'(Across top of salt Zone) 7. 10 sacks in top of 8-5/8" & 13-3/8" casing at surface 8. 5 sacks in rat & mouse holes 9. Weld steel plate on top of surface casing. 10. Erect permanent marker on top of steel plate. Plugging operations to begin on November 30, 1979. Verbal approval of above program received from Mr. J. T. Sexton 11/3		(C) -1	ates including estimated date of starting any proposed
Harold F. Burke		Hole to be filled with 9.4#/gal. dr follows through drillpipe by Hallibe 1. 35 sacks from 10,275'-10,375'(2. 35 sacks from 9945'-10,045'(Acrost 4. 35 sacks from 5540'-5640')Acrost 5. 35 sacks from 4150'-4250'(Acrost 6. 35 sacks from 2150'-2250'(Acrost 7. 10 sacks in top of 8-5/8" & 138. 5 sacks in rat & mouse holes 9. Weld steel plate on top of sur 10. Erect permanent marker on top of Plugging operations to begin on Nove	illing mud. To spot cement plugs a urton: Across top of Ranger Lake Zone) ross top of Bo-A Zone) ss top of Abo Zone) ss base of San Andres) ss base of 8-5/8" casing) ss top of salt Zone) -3/8" casing at surface face casing. of steel plate. ember 30, 1979.
Harold F. Burke	R. I hereby certify that the information abo	ve is true and complete to the best of my knowledge and beli-	ef.
Harold F Burke	1 2001		
DEC 18 1979	Harold E. De	TITLE AGENT	1/
	natulu E. Burke		DEC 18 1979