

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LC-3667	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		
1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator JFG ENTERPRISES		8. Farm or Lease Name Mescalero "PU" State
3. Address of Operator Box 100, Artesia, New Mexico 88210		9. Well No. 1
4. Location of Well UNIT LETTER <u>P</u> , <u>330</u> FEET FROM THE <u>East</u> LINE AND <u>330</u> FEET FROM THE <u>South</u> LINE, SECTION <u>15</u> TOWNSHIP <u>10 S</u> RANGE <u>32 E</u> NMPM.		10. Field and Pool, or Wildcat Mescalero San Andres
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Spot 60 sxs. Cement @ 4177'. Tagged plug @ 3927'. Circulated Hole w/Salt Jell.
- Spot 30 sxs. Cement @ 4 1/2" Stub @ 2650'. Tagged Plug @ 2510' Pulled 2609' of 4 1/2" Casing.
- Spot 50 sxs. Cement @ 2300' across Salt Base.
- Spot 60 sxs. Cement across 8 5/8" Shoe @ 1600' Tagged 8 5/8" Shoe Plug @ 1430'
- Spot 5 sxs Cement @ Surface - Erect Dry Hole Marker. Doing Cleanup.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED <u>J. T. Jackson</u>	TITLE <u>Agent</u>	DATE <u>5-23-83</u>	
APPROVED BY <u>Jack Griffin</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>AUG 27 1986</u>	
CONDITIONS OF APPROVAL, IF ANY:			