

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
LC-3667

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name	
2. Name of Operator	8. Farm or Lease Name	
JFG ENTERPRISES	Mescalero "PU" State	
3. Address of Operator	9. Well No.	
P.O. Box 100, Artesia, New Mexico 88210	1	
4. Location of Well	10. Field and Pool, or Wildcat	
UNIT LETTER <u>P</u> <u>330</u> FEET FROM THE <u>East</u> LINE AND <u>330</u> FEET FROM	Mescalero San Andres	
THE <u>South</u> LINE, SECTION <u>15</u> TOWNSHIP <u>10 S</u> RANGE <u>32 E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)	12. County	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spot 150' Plug @ Perf. @ 4055' - 4170'
2. Spot 150' Plug @ Base of Sale
3. Spot 50' Plug in and out of 4 1/2" casing @ approximately 2100'
4. Spot 100' Plug Base 8 5/8" (1600')
5. 10' Plug @ Surface
6. Install Dry Hole Marker and do cleanup.

ALL COPIES FROM THIS FORM MUST BE FILED BY 24
HOURS AFTER THE DATE OF THE ACTION OF
THE BOARD OF LANDS AND MINES
TO BE VALID.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED <u>J. T. Jackson</u>	TITLE <u>Partner</u>	DATE <u>5-6-83</u>	
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR			
APPROVED BY _____	TITLE _____	DATE <u>MAY 9 1983</u>	
CONDITIONS OF APPROVAL, IF ANY:			

RECEIVED

MAY 9 1983

O.C.D.
HOBBS OFFICE.