

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-28165
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. LC-1796-1
7. Lease Name or Unit Agreement Name State AR
8. Well No. 4
9. Pool Name or Wildcat Echols (Devonian)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3961' KB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator Lynx Petroleum Consultants, Inc.
3. Address of Operator P. O. Box 1979, Hobbs, NM 88241
4. Well Location Unit Letter <u>K</u> : <u>1950</u> Feet From The <u>South</u> Line and <u>1650</u> Feet From The <u>West</u> Line Section <u>2</u> Township <u>11S</u> Range <u>37E</u> NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

13 3/8" @ 368' 400 sx circ.
9 5/8" @ 5035' 1865 sx circ.
5 1/2" @ 11420' 1075 sx est. top 4150' ±

1. Set CIBP above perms and cap w/35' cement @ 11300'.
2. Load hole w/10# salt gel/25# per barrel.
3. Spot 100' plug top Abo 7600-7500'.
4. Cut & pull 5 1/2" casing. Put 100' plug @ stub - 50' in stub and 50' out of stub and tag.
5. Spot 100' plug top of salt 2200-2100'.
6. Spot 100' plug 418-318'.
7. 10 sx surface plug.
8. Install marker and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Zwick TITLE President DATE 3/20/91

TYPE OR PRINT NAME

TELEPHONE NO

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL IF ANY