30-025-29525 STATE OF NEW MEXICO NERGY AND MINERALS DEPARTMENT **OIL CONSERVATION DIVISION** form C-101 Revised 10-1-78 P. O. BOX 2088 DISTRIBUTION SA. Indicate Type of Lease SANTA FE, NEW MEXICO 87501 SANTA FE BTATE FILE 5. State Oil 6 Gas Leane No. U.S.G.S. LAND OFFICE OPERATOR APPLICATION FOR PERMIT TO DRILL, DEEPEN, OR PLUG BACK Type of Work 7. Unit Agreement Name DRILL X DEEPEN PLUG BACK 8. Farm or Lease Name b. Type of Well Sir X SINGLE X MULTIPLE Robinson 14 9. Well No. . Name of Operator Tenneco Oil Company 10. Field and Pool, on Wildcat Address of Operator 7990 IH 10 West, San Antonio, TX 78230 Vada . Location of Well P LOCATED_ 660' 660 12. County 19A. Formation 20. Recury or C.T. Bough "C" 97501 Rotary 21B. Drilling Contractor 22. Approx. Date Work will start 21A. Kind & Status Plug. Bond 4341.0 GR blanket unknown December 5, 1985 PROPOSED CASING AND CEMENT PROGRAM SIZE OF CASING WEIGHT PER FOOT SETTING DEPTH SACKS OF CEMENT SIZE OF HOLE EST. TOP 13 3/8" 17 ½" 54.5# 4001 425 sxs Class C surface 12 ½" 8 5/8" 2370**'** 32# 2525 sxs Class C surface 97501 -7 7/8" 17# 595 sxs Class H 6800' MIRU drilling rig. Spud w/17 1/2" bit. Drill to 400' w/spud mud. Possible loss of full returns can be encountered. Dry drill if full returns cannot be regained. Prior to POOH to run casing, pump Hi-Vis sweep and spot 80-100 bbl pill on bottom. Run and cement 13 3/8" casing as directed in casing-cement program. After sufficient WOC time CO/13 3/8 casing and weld on 13 $3/8 \times 13 5/8 - 3M$ flange to casing. NU BOP diverter system as described in BOP schematic for intermediate hole. 5. PU 12 1/4" bit. RIH to top of baffle collar. Test casing - BOPE to 500 psi (30 min). Drill out F/E to top of guide shoe. Test casing to 500 psi.
6. Drill 12 1/4" hole to 3870' (top of San Andres). Drill through inner reserve pit (See Mud Program). Make wiper trip prior to POOH to run casing. Permit Expires 6 Months From Approval Date Unless Drilling Underway. that the information above is true and complete to the best of my knowledge and belief.

DEC 4 - 1985

(This space for State Use)

ORIGINAL SIGNED BY JESRY SEXTON

7. Run and cement 8 5/8" casing as directed casing-cement program.

weight on bottom.

8. CO 13 3/8" casing flange. ND diverter system. Before CO 8 5/8" casing, make sure pipe is cmt to surface. CO 8 5/8" csg. Weld on 8 5/8 slip on x 8 5/8 8RD bell nipple. Install casing section of Unistack. (NOTE: Do not CO casing until cement has set.)

NU BOPE as specified in BOP Schematic.

- 10. PU 7 7/8" bit. RIH to top of FE. Test casing and BOPE to 1000 psi (30 min). Witness all tests.
- problems.)

12. Log as directed by G.E. DST possible in Bough "C" (9610').

- 13. If decision is made to run pipe, run 5 1/2" casing to 9750'. Cement as directed in cement program. Set 20% casing weight on bottom, 80% on slips (tension).
- 14. ND BOPE. CO 5 1/2" casing. Install tubing section of Unistack. Test same to 50% casing collapse.

RECEIVED

A STORY OF THE STATE OF THE STATE OF