

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-29969
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L.G. 1041
7. Lease Name or Unit Agreement Name Kellahin 14 State
8. Well No. 2
9. Pool name or Wildcat South Flying M-Abe

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Spence Energy Company
3. Address of Operator 4849 Greenville Ave Ste#381 Dallas, Texas 75206	4. Well Location Unit Letter P : 330 Feet From The South Line and 700 Feet From The East Line Section 14 Township 9S Range 32E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4336 G.L.	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Set 100' Plug 50' above 3530'
- 2) Set 100' Plug from 1622'-1740'
- 3) Set 10 sxs Plug at surface.

WILL NEED TO PERF AT 5 1/2" @ 1740 & PUT 200' OF CEM  
OUT SIDE OF PIPE & 100' INSIDE PIPE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Clay Spence TITLE Production Forman DATE 4-1-92  
TYPE OR PRINT NAME Clay Spence TELEPHONE NO. 214-739-0027

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: