

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30 025 30858
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-2174
7. Lease Name or Unit Agreement Name STATE "26"
8. Well No. 3
9. Pool name or Wildcat Vada (Devonian)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4195.8' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Western Reserves Oil Co., Inc.
3. Address of Operator P.O. Box 993 Midland, Texas 79702	4. Well Location Unit Letter <u>K</u> : <u>1,650</u> Feet From The <u>South</u> Line and <u>2.310</u> Feet From The <u>West</u> Line Section <u>26</u> Township <u>10S</u> Range <u>33E</u> NMPM <u>Lea</u> County <u></u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4195.8' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Work Performed 1-22-96 through 1-26-96

1. RIH to 12,500'
2. Circ. hole 300 Bl 10# Brine w/150 sks sw get
3. Spot 10 sxc
4. Spot 25 sxc 8850' - 8600'
5. Cut casing @ 4150'
6. Spot plug @ 5400' w/25 sxc 5400' - 5148'
7. Spot plug @ 4400' w/100 sxc 4400' - 3874'
8. Tag plug @ 3902'
9. 35 sxc 1950' - 1821'
10. 10 sxc @ surf.
11. Install dry hole marker

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Christopher P. Renaud TITLE Agent DATE 2-20-96

TYPE OR PRINT NAME Christopher P. Renaud TELEPHONE NO. 915 683-5533

(This space for State Use)

APPROVED BY GARY W. WINK TITLE DATE JAN 14 2003

CONDITIONS OF APPROVAL: REPRESENTATIVE II/STAFF MANAGER

17115192
Received
Hobbs
000
15878910