

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30994
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Hileman
2. Name of Operator Grand Banks Energy Company	8. Well No. 1
3. Address of Operator P.O. Box 51237, Midland, Texas 79710-1237	9. Pool name or Wildcat Wildcat
4. Well Location Unit Letter J : 2100 Feet From The South Line and 2100 Feet From The East Line Section 13 Township 9S Range 34E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4195' GRD	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Start date February 1, 1991

Set CIBP @ 8900' w/ 20' cmt of top.

Cut and attempt to pull 5 1/2" csg @ 6500' (TOC @ 7050').

Set 100' cmt plug in and out of stub w/ tbg.

Set 100' cmt plug across 8 5/8" csg shoe @ 4000'.

Cut and attempt to pull 8 5/8" csg @ 2000' (TOC @ 2400').

Set 100' cmt plug across 12 3/4" csg shoe @ 430' w/ tbg.

Set 10 sxs plug @ surface w/ tbg.

Set dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Carlton Wheeler TITLE V.P.-Operations DATE 1-10-91

TYPE OR PRINT NAME Carlton Wheeler TELEPHONE NO. 915/682-1044

(This space for State Use)

APPROVED BY ORIGINAL DONALD A. ARBY SEXTON TITLE MANAGER DATE JAN 14 1991

CONDITIONS OF APPROVAL, IF ANY: