Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

OIL CONSERVATION DIVISION

	NM 88240	P.O. Box	2088	WELL API NO.
DISTRICT II		Santa Fe, New Mexi		30-025-31061
P.O. Drawer DD, Artesi DISTRICT III	L NM 88210		•	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., A	ziec, NM 87410			6. State Oil & Gas Lease No. L-332
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"				7. Lease Name or Unit Agreement Name
Dil 1. Type of Well:		IR. USE "APPLICATION FOR) FOR SUCH PROPOSALS.)		
WELL XX	GAS WELL	OTHER		Sunray -A-, 6822 Ltd
Name of Operator				8. Well No.
BTA Oil Proc Address of Operator				9. Pool name or Wildcat
•	s, Midland, T	v 70701		Lane (San Andres)
L Well Location	s, midiand, i	X 79701		Lane (San Andres)
Unit Letter _	G: 1980	Feet From The North	Line and 1	980 Feet From The East Line
Section	36	Township 9S	Range 33E ether DF, RKB, RT, GR, etc.)	NMPM Lea County
			4291 ' RKB	
11.		• •	ate Nature of Notice, R	
NO	TICE OF INTE	NTION TO:	SUB	SSEQUENT REPORT OF:
ERFORM REMEDIAL	. WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
EMPORARILY ABAN	DON	CHANGE PLANS	COMMENCE DRILLING	
PULL OR ALTER CAS	ING 📋	-	CASING TEST AND CI	EMENT JOB XX
THER:		L	OTHER:	t
12. Describe Proposed of work) SEE RULE 1		(Clearly state all pertinent detai	ils, and give pertinent dates, inclu	ding estimated date of starting any proposed
12-29-90	Spudded @ 9:0	0 p.m., Drlg 12-1	/4" hole	
	6 hrs, Instal to 1000 psi f	led csg head & BO or 30 min on fres	P's, Cleaned out	w/300 sx cmt circ, WOC to shoe, Tstd BOP's & csg total then drld shoe.
	6 hrs, Instal to 1000 psi f Drlg 7-7/8" h	led csg head & BO or 30 min on fres	P's, Cleaned out h wtr, WOC 12 hrs	to shoe, Tstd BOP's & csg
	6 hrs, Instal to 1000 psi f Drlg 7-7/8" h	led csg head & BO or 30 min on fres	P's, Cleaned out h wtr, WOC 12 hrs	to shoe, Tstd BOP's & csg
<u>1-2-91</u>	6 hrs, Instal to 1000 psi f Drlg 7-7/8" h	led csg head & BO or 30 min on fresole. Drlg 7-7/8" hole.	P's, Cleaned out h wtr, WOC 12 hrs	to shoe, Tstd BOP's & csg
<u>1-2-91</u>	6 hrs, Instal to 1000 psi f Drlg 7-7/8" h	led csg head & BO or 30 min on fresole. Drlg 7-7/8" hole.	P's, Cleaned out h wtr, WOC 12 hrs	to shoe, Tstd BOP's & csg
1-2-91	6 hrs, Instal to 1000 psi f Drlg 7-7/8" h	led csg head & BO or 30 min on fres ole. Drlg 7-7/8" hole.	P's, Cleaned out h wtr, WOC 12 hrs	to shoe, Tstd BOP's & csg total then drld shoe. dministrator DATE 1-2-91
1-2-91 I beneby certify that the in	Dorothy Ho	led csg head & BO or 30 min on fres cole. Drlg 7-7/8" hole. Dughton MISS BY JERRY SEXTON	P's, Cleaned out h wtr, WOC 12 hrs	to shoe, Tstd BOP's & csg total then drld shoe.
1-2-91 I bereby conify that the its signature TYPE OR PRINT NAME	Dorothy Ho	led csg head & BO or 30 min on fres ole. Drlg 7-7/8" hole.	P's, Cleaned out h wtr, WOC 12 hrs	to shoe, Tstd BOP's & csg total then drld shoe. dministrator DATE 1-2-91