

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31104
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-1041
7. Lease Name or Unit Agreement Name Kellahin 14 State
8. Well No. 4
9. Pool name or Wildcat South Flying M-Bough

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Spence Energy Co
3. Address of Operator 4849 Greenville Ave Ste #381 Dallas, Texas 75206	4. Well Location Unit Letter <u>P</u> : <u>980'</u> Feet From The <u>South</u> Line and <u>330'</u> Feet From The <u>East</u> Line Section <u>14</u> Township <u>9S</u> Range <u>32E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4336.4 GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1) Cut 8 5/8" Surface Casing @ 700'
2) Cut 4 1/2" Production Casing @ 4500'
3) Set 100' plug @ 8 5/8" Cut off
4) Set 100' plug, 50' in & 50' out of surface Casing shoe
5) Set 10 Sks plug @ surface.
6) Starting date is when the C-103 form is accepted by the Oil Conservation Commission.

set 100 plug @ 8800 Tay
100 plug @ 6760
4500 stat plug 4 1/2 50 in / 50 out Tay
100 plug 2200

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Clay Spence TITLE Production Analysis DATE 1-13-92

TYPE OR PRINT NAME Clay Spence TELEPHONE NO. 214-739-0027

(This space for State Use)

Orig. Signed by Paul Kautz Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: _____

JAN 17 '92