

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31497
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name  Cooper 24
8. Well No. 1
9. Pool name or Wildcat South Flying M-Abo

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Spence Energy Co.	
3. Address of Operator 4849 Greenville Ave Ste#381 Dallas, Texas 75206	
4. Well Location Unit Letter <u>D</u> : <u>500</u> Feet From The <u>West</u> Line and <u>330</u> Feet From The <u>North</u> Line Section <u>24</u> Township <u>9S</u> Range <u>32E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4336.4	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set 100' plug across Perf. 8282-8328 It has allready been done.

- 1) Fill hole w/ Mud.
- 2) Cut Casing of @ 5300'
- 3) Set 100' Plug 50' in & 50' out of 5 1/2 cut of. 709
- 4) Set 100' plug @ top of San Andres formation
- 5) Set 100' plug @ bottom of Surface casing (1661') 709
- 6) Set 100' plug @ 650'
- 7) Set 10 sx. plug at surface
- 8) Make 4' marker w/ appropriate information.
- 9) level all pits & Cut dead man off.

THE COMMISSION MUST BE NOTIFIED 24  
HOURS BEFORE THE BEGINNING OF  
PROPOSED OPERATIONS FOR THE CHOS  
TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Clay Spence TITLE Prod. Analysis DATE 6-24-92  
TYPE OR PRINT NAME CLAY Spence TELEPHONE NO. 214-739-0027

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
JUN 9 1992

RECEIVED  
JUN 10 1992  
JUN 10 1992