Submit 3 50, 'es App. 17 C, ale istrict L, fice	State of New Mexico Energy, Minerals and Natural Resources Department		Form C-103 Revised 1-1-89 WELL API NO.		
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	Santa Fe, New Mexico 87504-2088				
DISTRICT II P.O. Drawer DD, Artesia, NM 88210			30-0 5. Indicate Type of	025-34859	
DISTRICT III					STATE FEE
1000 Rio Brazos Ed., Aziec, NM 87410				6. State Oil & Ga	NO-5606
(DO NOT USE THIS FORM FOR PF DIFFERENT RESE	TICES AND REPORTS ON ROPOSALS TO DRILL OR TO DE ERVOIR. USE "APPLICATION R C-101) FOR SUCH PROPOSALS	EEPEN (OR PEF	OR PLUG BACK TO A	7. Lease Name of	r Unit Agreement Name
1. Type of Well: OL GAS WEL X WELL				Blitzer	n AUB State
2. Name of Operator				8. Well No.	2
YATES PETROLEUM CORPO 3. Address of Operator	KATION		<u></u>	9. Pool name or	
105 South 4th St., Ar 4. Well Location	tesia, NM 88210			Wildcat	Devonian
	00 Feet From The South	1	Line and850	Feet From	m The East Line
Section 16	Township 11S	Rai vhether L	nge 34E DF, RKB, RT, GR, etc.)	NMPM	Lea County
			O' GR		
11. Check NOTICE OF IN	Appropriate Box to Indi	icate r			REPORT OF:
٦	ILMION IO.	_	002		Г. ОТТ ОТТ
			PEUEDIAL INODIC	1 1	
— 1	PLUG AND ABANDON				
	PLUG AND ABANDON CHANGE PLANS				ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING		PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING CASING TEST AND CE OTHER: Prep for	drilling r	PLUG AND ABANDONMENT
EMPORARILY ABANDON	CHANGE PLANS	L	COMMENCE DRILLING CASING TEST AND CE OTHER: Prep for	drilling r	PLUG AND ABANDONMENT
TEMPORARILY ABANDON Image: Complete the completet the complete the complete the complete the completet	CHANGE PLANS	ig .un	COMMENCE DRILLING CASING TEST AND CE OTHER: Prep for d give pertinent dates, inclu it. Bled tubin	drilling random date of g down. Swa	PLUG AND ABANDONMENT
TEMPORARILY ABANDON Image: Complete and the second sec	CHANGE PLANS rations (Clearly state all periment de and rigged up pullin led down tree and ni	ng.un Lpple	COMMENCE DRILLING CASING TEST AND CE OTHER: Prep for d give pertinent dates, inclu it. Bled tubin d up BOP. Rele	drilling r drilling r ding estimated date of g down. Swa ased packer	PLUG AND ABANDONMENT
TEMPORARILY ABANDON Image: Complete A comp	CHANGE PLANS rations (Clearly state all persinent de and rigged up pullin led down tree and ni laying tubing down. unit. Released well	ng.un ipple Nip L to	COMMENCE DRILLING CASING TEST AND CE OTHER: Prep for d give periment dates, inclu it. Bled tubin d up BOP. Rele pled down BOP a drilling depart	drilling ri drig estimated date of g down. Swa ased packer nd nippled u	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS rations (Clearly state all periment de and rigged up pullin led down tree and ni laying tubing down. unit. Released well . Dig rat and mouse	Nip L to hol	COMMENCE DRILLING CASING TEST AND CE OTHER: Prep for d give pertinent dates, inclu it. Bled tubin d up BOP. Rele pled down BOP a drilling depart es.	drilling ri drig estimated date of g down. Swa ased packer nd nippled u	PLUG AND ABANDONMENT
<pre>FEMPORARILY ABANDON PULL OR ALTER CASING DTHER: I2 Describe Proposed or Completed Ope work) SEE RULE 1103. 8-3-2000 - Moved in Loaded tubing. Nipp tubing down. 8-4-2000 - Finished Rigged down pulling 8-5-2000 - TD 13089' 8-6-2000 - TD 13089' 8-8-2000 - TD 13089'</pre>	CHANGE PLANS rations (Clearly state all periment de and rigged up pullim led down tree and ni laying tubing down. unit. Released well . Dig rat and mouse . Moving in rotary . Nippling up BOP's . Testing BOP & pip	Nip Nip tool tool s. F	COMMENCE DRILLING CASING TEST AND CE OTHER: Prep for d give pertiment dates, inclu it. Bled tubin d up BOP. Rele pled down BOP a drilling depart es. s. inished moving ms. Tested bli	Arilling random data and an and rigg and rand rigg.	PLUG AND ABANDONMENT
<pre>FEMPORARILY ABANDON PULL OR ALTER CASING DTHER: I2 Describe Proposed or Completed Ope work) SEE RULE 1103. 8-3-2000 - Moved in Loaded tubing. Nipp tubing down. 8-4-2000 - Finished Rigged down pulling 8-5-2000 - TD 13089' 8-6-2000 - TD 13089' 8-7-2000 - TD 13089' 8-8-2000 - TD 13089'</pre>	CHANGE PLANS rations (Clearly state all persistent de and rigged up pulling led down tree and ni laying tubing down. unit. Released well . Dig rat and mouse . Moving in rotary . Nippling up BOP's . Testing BOP & pip lly and installed ke	Nip Nip tool tool s. F pe ra elly	COMMENCE DRILLING CASING TEST AND CE OTHER: Prep for d give periment dates, inclu it. Bled tubin d up BOP. Rele pled down BOP a drilling depart es. s. inished moving ms. Tested bli valves and driv	EMENT JOB	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS rations (Clearly state all persinent de and rigged up pullin led down tree and ni laying tubing down. unit. Released well . Dig rat and mouse . Moving in rotary . Nippling up BOP's . Testing BOP & pip lly and installed ke and TlH. Set packe . Waiting on freepo	Nip Nip tool tool tool s. F be ra elly er an	COMMENCE DRILLING CASING TEST AND CE OTHER: Prep for d give periment dates, inclu it. Bled tubin d up BOP. Rele pled down BOP a drilling depart es. s. inished moving ms. Tested bli valves and driv d tested pipe r truck. Tested	drilling raised date of down. Swa ased packer and nippled a ment.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS rations (Clearly state all periment de and rigged up pullim led down tree and ni laying tubing down. unit. Released well . Dig rat and mouse . Moving in rotary . Nippling up BOP's . Testing BOP & pip lly and installed ke and TlH. Set packe . Waiting on freepo and drillpipe. Inst	Nip Nip tool tool tool s. F be ra elly er an oint	COMMENCE DRILLING CASING TEST AND CE OTHER: Prep for d give periment dates, juctu it. Bled tubin d up BOP. Rele pled down BOP a drilling depart es. s. inished moving ms. Tested bli valves and driv d tested pipe r truck. Tested d rotating head	drilling rained date of diag estimated date of	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS rations (Clearly state all periment de and rigged up pullim led down tree and ni laying tubing down. unit. Released well . Dig rat and mouse . Moving in rotary . Nippling up BOP's . Testing BOP & pip lly and installed ke and TlH. Set packe . Waiting on freepo and drillpipe. Inst lated & worked pipe.	Nip Nip to hol tool tool s. F be ra elly er an oint talle St bedge md	COMMENCE DRILLING CASING TEST AND CE OTHER: Prep for d give periment dates, includ it. Bled tubin d up BOP. Rele pled down BOP a drilling depart es. s. inished moving ms. Tested bli valves and driv d tested pipe r truck. Tested d rotating head uck while circu	drilling r: ding estimated date of g down. Swa ased packer and nippled u ment. in and rigg and rams and e bushing. ams. pipe rams and rubber. Wa lating bott.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS rations (Clearly state all periment de and rigged up pullim led down tree and ni laying tubing down. unit. Released well . Dig rat and mouse . Moving in rotary . Nippling up BOP's . Testing BOP & pip lly and installed ke and TlH. Set packe . Waiting on freepo and drillpipe. Inst lated & worked pipe.	Nip Nip to hol tool tool s. F be ra elly er an oint talle St bedge md	COMMENCE DRILLING CASING TEST AND CE OTHER: Prep for d give periment dates, includ it. Bled tubin d up BOP. Rele pled down BOP a drilling depart es. s. inished moving ms. Tested bli valves and driv d tested pipe r truck. Tested d rotating head uck while circu	drilling r: ding estimated date of g down. Swa ased packer and nippled u ment. in and rigg and rams and e bushing. ams. pipe rams and rubber. Wa lating bott.	PLUG AND ABANDONMENT
<pre>FEMPORARILY ABANDON PULL OR ALTER CASING DTHER: I2 Describe Proposed or Completed Ope work) SEE RULE 1103. 8-3-2000 - Moved in Loaded tubing. Nipp tubing down. 8-4-2000 - Finished Rigged down pulling 8-5-2000 - TD 13089' 8-6-2000 - TD 13089' 8-6-2000 - TD 13089' 8-8-2000 - TD 13089' 8-8-2000 - TD 13089' 5000#. Picked up ke and 3-1/2" drillpipe 8-9-2000 - TD 13089' TIH with 6-1/8" bit with no fill. Circu Ihereby certify the the information at one information.</pre>	CHANGE PLANS rations (Clearly state all periment de and rigged up pullim led down tree and ni laying tubing down. unit. Released well . Dig rat and mouse . Moving in rotary . Nippling up BOP's . Testing BOP & pip lly and installed ke and TlH. Set packe . Waiting on freepo and drillpipe. Inst lated & worked pipe. m and complete to the best of my knowl	Nip Nip to hol tool tool s. F be ra elly er an oint talle St bedge md	COMMENCE DRILLING CASING TEST AND CE OTHER: Prep for d give periment dates, includ it. Bled tubin d up BOP. Rele pled down BOP a drilling depart es. s. inished moving ms. Tested bli valves and driv d tested pipe r truck. Tested d rotating head uck while circu	drilling r: ding estimated date of g down. Swa ased packer and nippled u ment. in and rigg and rams and e bushing. ams. pipe rams and rubber. Wa lating bott.	PLUG AND ABANDONMENT
<pre>FEMPORARILY ABANDON PULL OR ALTER CASING DTHER: I2 Describe Proposed or Completed Ope work) SEE RULE 1103. 8-3-2000 - Moved in Loaded tubing. Nipp tubing down. 8-4-2000 - Finished Rigged down pulling 8-5-2000 - TD 13089' 8-6-2000 - TD 13089' 8-6-2000 - TD 13089' 8-8-2000 - TD 13089' 8-8-2000 - TD 13089' 5000#. Picked up ke and 3-1/2" drillpipe 8-9-2000 - TD 13089' TIH with 6-1/8" bit with no fill. Circu I hereby certify the the information at one information SKONATURE Puesty Klap </pre>	CHANGE PLANS rations (Clearly state all periment de and rigged up pullim led down tree and ni laying tubing down. unit. Released well . Dig rat and mouse . Moving in rotary . Nippling up BOP's . Testing BOP & pip lly and installed ke and TlH. Set packe . Waiting on freepo and drillpipe. Inst lated & worked pipe. m and complete to the best of my knowl	Nip Nip to hol tool tool s. F be ra elly er an oint talle St bedge md	COMMENCE DRILLING CASING TEST AND CE OTHER: Prep for d give periment dates, includ it. Bled tubin d up BOP. Rele pled down BOP a drilling depart es. s. inished moving ms. Tested bli valves and driv d tested pipe r truck. Tested d rotating head uck while circu	drilling r: ding estimated date of g down. Swa ased packer and nippled u ment. in and rigg and rams and e bushing. ams. pipe rams and rubber. Wa lating bott.	PLUG AND ABANDONMENT
<pre>FEMPORARILY ABANDON DULL OR ALTER CASING DTHER: I2 Describe Proposed or Completed Ope work) SEE RULE 1103. 8-3-2000 - Moved in Loaded tubing. Nipp tubing down. 8-4-2000 - Finished Rigged down pulling 8-5-2000 - TD 13089' 8-6-2000 - TD 13089' 8-6-2000 - TD 13089' 8-8-2000 - TD 13089' 8-8-2000 - TD 13089' 5000#. Picked up ke and 3-1/2" drillpipe 8-9-2000 - TD 13089' TIH with 6-1/8" bit with no fill. Circu Ihereby certify that the information a cyclef shonature Rusty Kle</pre>	CHANGE PLANS rations (Clearly state all periment de and rigged up pullim led down tree and ni laying tubing down. unit. Released well . Dig rat and mouse . Moving in rotary . Nippling up BOP's . Testing BOP & pip lly and installed ke and TlH. Set packe . Waiting on freepo and drillpipe. Inst lated & worked pipe. m and complete to the best of my knowl	Nip L to L to	COMMENCE DRILLING CASING TEST AND CE OTHER: Prep for d give periment dates, includ it. Bled tubin d up BOP. Rele pled down BOP a drilling depart es. s. inished moving ms. Tested bli valves and driv d tested pipe r truck. Tested d rotating head uck while circu	drilling r: ding estimated date of g down. Swa ased packer and nippled u ment. in and rigg and rams and e bushing. ams. pipe rams and rubber. Wa lating bott.	PLUG AND ABANDONMENT

YATES PETROLEUM CORPORATION Blitzen AUB State #2 Section 16-T11S-R34E Lea County, New Mexico

SUNDRY NOTICE CONTINUED:

drilling. Cannot rotate or circulate.
8-10-2000 - TD 13i29'. Circulating samples. Made 40'. Rigged up freepoint and run freepoint. Pipe came free while running freepoint. Pulled 3 joints into casing. Rigged down freepoint truck. Circulated and conditioned mud. Washed 90' to bottom. Took 5K at 13059'. No fill on bottom. Drilled to 13129'. Circulated samples. Resumed operations with rotary tools at 8:00 PM 8-9-2000.
8-11-2000 - TD 13139'. Reached TD at 7:00 AM 8-10-2000 (6-1/8" hole). Ran logs.
8-12-2000 - TD 13139'. Set a cement plug as follows: 100 sacks Class H cement at 13118'. PD 7:30 PM 8-11-2000. TOOH with 8 stands of drillpipe. Reverse circulated drillpipe volume. TOOH with drillpipe. WOC.
8-13-2000 - TD 13000'. TIH and tagged cement at 12775'. Picked up kelly and installed rotating rubber. Drilled cement from 12775-13000'. Circulated and TOOH. Rigged up wireline truck and ran collar locator. Indicated casing shoe at 12992'.
8-14-2000 - Time drilling at 13001' (4-3/4" hole).

8-28-2000 - TD 14232'. Reached TD at 6:45 PM 8-27-2000 (4-3/4" hole).
8-29-30-2000 - TD 14232'. Waiting on orders.
8-31-2000 - TD 14232'. Laying down drillpipe. TIH and laid down 3 joints drillpipe.
Picked up swivel and washed to bottom. Took 10K at 13008'. Tagged bridge at 14088'.
Took 25K string weight - packed off and worked free. Washed 135' to bottom. Circulate and condition mud. Displaced lateral hole with 2% KCL fluid. Rigged down swivel.
Displaced caisng with 2% KCL water. Laying down drillpipe.
9-1-2000 - TD 14232'. Rigging down rotary tools. Finished laying down drillpipe and 2-7/8" tubing. Changed out pipe rams. Laid down BOP. Nippled up tubing head and B-1 adapter flange. Changed out liner on pumps. Released rig at 3:00 AM 9-1-2000.

Waiting on completion unit.

Rusty Klein Operations Technician September 30, 2000