Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources D	Department	Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		LL API NO.
DISTRICT II			30-025-34942 5. Indicate Type of Lease
P.O. Drawer DD, Artesia, NM 88210 DISTRICT III		ļ	
1000 Rio Brazos Rd., Aztec, NM 8741	0	6.	State Oil & Gas Lease No. VA-1338
( DO NOT USE THIS FORM FOR DIFFERENT RE	DTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG SERVOIR. USE "APPLICATION FOR PERMIT" A C-101) FOR SUCH PROPOSALS.)	BACK TO A 7.	Lease Name or Unit Agreement Name
1. Type of Well: OB. QAS WELL X WELL	OTHER		Hytech AUM State
2. Name of Operator		8.	Well No.
YATES PETROLEUM CORP	ORATION		2 Pool name or Wildcat
3. Address of Operator 105 South 4th St., A	rtesia, NM 88210	У.	Wildcat Devonian
4. Well Location			Wilded Devenium
Unit Letter $\underline{J}$ : $\underline{2}$	150 Feet From The South Lin	e and <u>1650</u>	Feet From The Line
Section 2	Township 10S Range	34E NMP	M. Lea County
	10. Elevation (Show whether DF, RKB, R	T, GR, etc.)	
	k Appropriate Box to Indicate Nature o		
NOTICE OF I	NTENTION TO:	SUBSE	QUENT REPORT OF:
		AL WORK	ALTERING CASING
		AL WORK NCE DRILLING OPI	
			NS. PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS COMME	NCE DRILLING OP TEST AND CEMEN Drill	NS. PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS COMME	NCE DRILLING OP! TEST AND CEMEN Drill ment dates, including e	NS. PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS COMME CASING CASING CASING OTHER: perations (Clearly state all pertinent details, and give pertinent 5' of new hole (12-1/4"). TD 3	NCE DRILLING OP! TEST AND CEMEN Drill ment dates, including e	NS. PLUG AND ABANDONMENT
I hereby certify that the information above i SIONATURE	CHANGE PLANS COMME CASING CASING CASING OTHER: perations (Clearly state all pertinent details, and give pertinent 5' of new hole (12-1/4"). TD 3	NCE DRILLING OP! TEST AND CEMEN Drill nent dates, including e 5'. Shut do	NS. PLUG AND ABANDONMENT