

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. #8875
7. Lease Name or Unit Agreement Name STATE "L"
8. Well No. #1
9. Pool name or Wildcat South Prairie San Andres

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator M & W OF LOVINGTON, INC.	
3. Address of Operator BOX 922, LOVINGTON, NM 88260	
4. Well Location Unit Letter M : 600 Feet From The 8 Line and 600 Feet From The 60 Line Section 16 Township 8 Range 36 NMPM County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Move in and rig up
- 2) POOH with rods & tbg
- 3) POOH with casing. 4-1/2" csg 4323' LT&C 11.6#/ft.
- 4) TIH with tbg. Spot 150 sx from 4850' - 4199' - Tag
- 5) Spot 35 sx  $\pm$  2500' - 2000' top of salt
- 6) Spot 10 sx surface plug. Cut off wellhead. Erect dry hole marker. Rig down, move out.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE G.A. Baber TITLE P&A AGENT DATE 12/19/91  
TYPE OR PRINT NAME G.A. BABER TELEPHONE NO. 392-5516

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: