

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions  
verse side)Form approved  
Budget 1-1-69 No. 12-1-12

5. LEASE DESIGNATION AND SERIAL

NM - 02218

6. IF INDIAN, ALLOTTEE OR AGED

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

King Davis Federal

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Allison (Penn)

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

28-8S-37E

12. COUNTY OR PARISH

Roosevelt

13. STATE

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR  
David Fasken
3. ADDRESS OF OPERATOR  
608 First National Bank Building, Midland, Texas
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface
- Unit J, 1980' FSL and 1980' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4029' DF

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

(This well is the former Sam Boren No. 1 King Davis Federal) Well plugged as follows:

1. Spotted 30 sx. plug on top of wiper plug in 4 $\frac{1}{2}$ " csg. from 9350' up to 9100'.
2. Shot pipe off at 6146' and spotted 30 sx. plug from 6146' to 6019'.
3. Spotted 30 sx. plug at base of 7-5/8" intermediate 4325 up to 4200'.
4. Shot off 7-5/8" at 1200'.
5. Spotted 35 sx. plug 1258 - 1150'.
6. Spotted 50 sx. plug 450 - 340'.
7. Set 10 sx. surface plug and placed permanent marker on top.

Well P & A, 12-14-68

NOTED

JAN 16 1969

18. I hereby certify that the foregoing is true and correct

SIGNED

*Robert A. Angerine*

TOWN

Agent

DATE 1-14-69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

APR 18 1974

ARTHUR R. BROWN  
DISTRICT ENGINEER

\*See Instructions on Reverse Side