

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. LC-062178
7. Lease Name or Unit Agreement Name Milnesand Unit
8. Well No. 198
9. Pool name or Wildcat Milnesand (San Andres)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Breck Operating Corp.	
3. Address of Operator P.O. Box 911, Breckenridge, Texas 76024	
4. Well Location Unit Letter <u>M</u> : <u>660</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>13</u> Township <u>8S</u> Range <u>34E</u> NMPM <u>Roosevelt</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4250' (GR)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PROPOSED STATUS

- Set CIBP in 4-1/2" csg. @ 4500'-and dump 2 ^{35' cmt} sx. cmt. on top.
PERF & SET PLUG FROM 2000-2170
- Cut 4-1/2" csg. @ 431' and POOH. Pump 35 sx. cmt. plug from 481'-381' inside and out of 4-1/2" csg. stub and across the 8-5/8" csg. shoe @ 431'.
- Dump ^{16"} 3 sx. cmt. in 8-5/8" csg. from 13'-3'. Cut off 8-5/8" csg. 3' below surface, weld on cap, and construct dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Alum G. Spucan TITLE Petroleum Engineer DATE 12/28/89

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL: THE COMMISSION MUST BE NOTICED 2-HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE CIBP TO BE APPROVED.

JAN 09 1990