UNITED STATES N. M. OIL CONS. ICOMMISSION (May 1963) DEPARTMENT OF THE INTER OF CONSTITUTIONS ON TE- GEOLOGICAL SURVEY HOBBS, NEW MEXICO 88240	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SEBIAL XO. NM 58537
SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TEIBE NAME
Use "APPLICATION FOR I LIGHT IN THE PLANE	7. UNIT AGREEMENT NAME
OIL GAS WEUL WELL OTHER 2. NAME OF OPERATOR	8. FARM OR LEASE NAME
Petroleum Production Management, Inc.	Irex Federal
3. ADDRESS OF OPREATOR <u>Suite 200/Sutton Place Bldg. Wichita, Kansas 67202</u> 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements." See also space 17 below.)	1 10. FIELD AND POOL, OR WILDCAT Allison Penn
At sufface 1980'FWL & 660' FSL Sec. 20, T-8-S, R-37-E	ATTISON FEIN 11. SEC., T., R., M., OR BLK. AND SUBVEY OR ADBA Sec. 20, T-8-S, R-37-E
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
4051' DF	Roosevelt N.M.
16. Check Appropriate Box To Indicate Nature of Notice, Report, or C	Other Data
NOTICE OF INTENTION TO:	CENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE ABANDON* X SHOOTING OF ACIDIZING	ABANDONMENT*
REPAIR WELL CHANGE PLANS (Other) (Other) (Norg: Report results Completion or Recomp	s of multiple completion on Well letion Report and Log form.)
 Spot 25 sacks cement through tubing at 5742' depth to form maximum depth reached during reentry attempt. They plus 2. Load hole with salt gel mud. Spot 50 sacks cement at 4058' to form a 100' plug straddlic casing at 4008' depth. Tag top of cement. Spot 75 sacks cement at 4265' to form 100' plug straddlis shoe at 4215' depth. Tag top of cement. The form 100' plug straddlis shoe at 4215' depth. Tag top of cement. Spot 50 sacks cement at 2383' to form 100' plug straddlis shoe at 4215' depth. Tag top of cement. The form 100' plug straddlis shoe at 4215' depth. Tag top of cement. Spot 50 sacks cement at 2383' to form 100' plug across to 5. Spot 50 sacks cement in 9 5/8" casing to form a 50' plug across to 6. Spot 25 sacks cement in 9 5/8" casing to form a 50' plug 7. Erect dry hole marker. Clean and level location. Contact surface owner (James W. Smith) and make agreement disposition of location. 	Ing top of 5 1/2" ing 9 5/8" casing top of salt section. g at surface.
18. I hereby certify that the pregoing is the and correct SIGNED AMULTOESOFICE TITLE DISCREEFENTINGET	DATE 8-17-90
(This space for Federal or State office use)	APARTY
APPROVED BY TITLE TITLE	
	AUG 2 3 1899
*Son Instructions on Reverse Side	1 BENERSSER COMMENT

See Instructions on Reverse Side

REAL OF LAND MARAGEMENT &