

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
SMITH AND MARRS, INC.

3. Address of Operator  
1110 N. Big Spring Midland, Tx 79701

4. Well Location  
Unit Letter N : 660 Feet From The S Line and 1980 Feet From The W Line  
Section 29 Township 8S Range 37E NMPM Roosevelt County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
4045'

7. Lease Name or Unit Agreement Name

Hayes

8. Well No.

4

9. Pool name or Wildcat

Allison

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. We will notify the OCD prior to beginning plugging operations

- 1) Rig up pulling unit.
  - 2) Set CIBP at 9550' and cap with 35' cmt.
  - 3) Set 100' plug at Abo at 6898'.
  - 4) Run free point on 5 1/2" casing
  - 5) Cut and pull 5 1/2" casing and set 100' plug across stub 50' in and 50' out.
  - 6) Set 100' plug across 8 5/8" casing shoe 50' in and 50' out.
  - 7) Set 100' plug at top of Salt at 2337'
  - 8) Set 10 sx at surface, install dry hole marker, and clean location.
- \* Hole will be loaded with 10# gel.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE Agent DATE 5-8-91

TYPE OR PRINT NAME Michael L. Pierce TELEPHONE NO. 392-1915

(This space for State Use)

Orig. Signed by,  
Paul Kautz  
Geologist

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE MAY 09 1991

CONDITIONS OF APPROVAL, IF ANY: