

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

JAN 17 11 40 AM '67

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name -
2. Name of Operator Sunray DX Oil Company	8. Farm or Lease Name Nancy Watson
3. Address of Operator P. O. Box 1416 - Roswell, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER F , 1980 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 31 TOWNSHIP 8-S RANGE 34-E N.M.P.M.	10. Field and Pool, or Wildcat Clr. San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4314 GR.	12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Start plugging procedures December 5, 1966.
2. Load hole with mud.
3. Spot 25 sx. cmt plug across perfs (4650-4315).
4. Cut off 4 1/2 csg. @ 3853' & lay down csg, keeping hole loaded with mud.
5. Spot 25 sx. cmt. plug @ 3953'-3790' in & out of 4 1/2 csg. stub.
6. Place 10 sx. cmt. @ surface.
7. Install dry hole marker.
8. Remove surface equipment and clean location.
9. Job complete - December 10, 1966.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. F. Brawley TITLE District Engineer DATE 1-16-67

APPROVED BY John W. Kinyan TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: