		MISSING -	
	; L. S 1323		
Form 3160-5	UNITED STATES HOUDS, NEW MEXI		
	MENT OF THE INTERIOR	Budget Bureau No. 1004-0135 Expires: March 31, 1993	
BUREAU	OF LAND MANAGEMENT		
SUNDRY NO	FICES AND REPORTS ON WELLS	5. Lease Designation and Serial No.	
	to deepen or reentry to a different reservoir.	NM-03283 6. If Indian, Allottee or Tribe Name	
	R PEPMIT" for such proposals		
		-	
SUBMIT IN	TRIPLICATE	7. If Unit or CA, Agreement Designation	
		_	
1. Type of Well	8. Well Name and No.		
Oil Gas Well X Well Other			
2. Name of Operator	LMY Federal #1 9. API Well No.		
Yates Drilling Compan	9. API Well No. $30-041-00273$		
3.Address and Telephone No.			
<u>105 S. 4th St., Artes</u> 4. Location of Well (Footage, Sec., T., R., M., or Survey De	ia, NM 88210 (505-748-1471)		
4. Location of Well (Footage, Sec., T., R., M., or Survey De	11. County or Parish, State		
660' FNL & 660' FWL Sec	tion 33-85-37		
	Chit D	December NM	
12. CHECK APPROPRIATE BO	X(s) TO INDICATE NATURE OF NOTICE, F	Roosevelt County, NM	
TYPE OF SUBMISSION	TYPE OF ACTION	dioki, ok oniek DATA	
X Notice of Intent	X Abandonment	Change of Plans	
Subsequent Report		New Construction	
	Plugging Back	Non-Routine Fracturing	
Final Abandonment Notice	Altering Casing	Water Shut-Off	
		Dispose Water	
		(Note : Report results of multiple completion on Well completion or Recompletion Report and Log Form)	
 Describe Proposed or Completed Operations (Clearly st give subsurface locations and measured and true vertical dep 	ate all pertinent details, and give pertinent dates, including estin	mated date of starting any proposed work. If well is directionally drilled,	
	tbg. to +/- 8200', TOH.		
	', spot 25 sack cement plug,	тон	
	ate @ +/- 4270', 2380', 401'		
		e through retainer w/43 sacks	
of cement, dump 7 sacks		s chitough roburner wy 45 oueks	
		e through retainer w/ 43 sacks of	
cement, dump 7 sacks on			
6. Pump down 4 1/2" casing	, try to break circulation to	o surface, squeeze through	
	0 sacks of cement, leave 10 s	sacks in 4 1/2" casing. 📑	
7. Spot 5 sacks surface pl	9		
8. Erect regulation surfac			
9. Remove equipment and cl	ean location.		
	1 . 11 . 1	10	
NOTE: Mud will be spotted	between all cement plugs.		
14 TI 1 (C 0 + 0 C 1 + 1 + 1			

(This space for Federal or State office use)		oleum Enginepr	CHESTER	
Approved by	Title	1	Dale	
Conditions of approval, if any:		APR	4 1995	
le 18 U.S.C. Section 1001, makes it a crime for any person resentations as to any matter within its jurisdiction.	knowingly and willfully to	ROSWELAND ROSWELAND e Instruction on Reverses	ncy of the United States as	y false, fictitious or fraudulent statements or

E	UREAU OF L. D MANA	INTERIOR P. O. BOX 1		Nri-03203	
SUNDRY	NOTICES AND REP r proposals to drill or to deeper PPLICATION FOR PERMIT-"	HOBBS, NEV ORTS ON WELLS in or plug back to a different r for such proposals.)		140 INDIAN, ALLOTTER OR TH	RIBE NAM
		6		7. UNIT AGREEMENT NAME	
NAME OF OPERATOR	filt.			- 3. FARM OR LEASE NAME	
Yates Drilling Co	ompany			LMY Federal-	
105 South 4th St	ceet, Artesia, NM	88210). WHLL NO. 1	
LOCATION OF WELL (Report lo See also space 17 below.)	cation clearly and in accordance	e with any State requirements.	• 1	10. FIELD AND POOL, OR WILD	CAT
At surface 660' FNL &	660' FWL	\mathcal{D}		Allison Penn 11. SBC., T., B., M., OR BLK. AN SURVEY OR ARMA	73>
				33-85-37E	
PERMIT NO.	403	whether DF, RT, GR, etc.)		12. COUNTY OR PARISE 13. 1 Roosevelt NM	
Che	ck Appropriate Box To Ir				<u>.</u>
	F INTENTION TO :			T REPORT OF :	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHO	r-orr	REPAIRING WELL	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE T		ALTEBING CASING	
BIDOT OB ACIDIZE	ABANDON* Change plans		R ACIDIZING	ABANDON MENT*	
••	l Perforations	X (Norr Compl	: Report results of etion or Recompleti	multiple completion on We on Report and Log form.)	11
DESCRIBE PROPOSED OR COMPLI	THE ADDRUGTIONS (Clearly state)	منام المستلك والمقداء فتحمط المستحد الم	pertinent dates, in	cluding estimated date of at	tarting a
proposed work. If well is nent to this work.)• Set CIBP above e: Perforate and ac: Swab test.	directionally drilled, give subst kisting perforation idize 9532'-9536' (ction as warranted.	urface locations and measured " s 9570'-9579' (Bou Bough B)	and true vertical (depths for all markers and :	çones pe:
proposed work. If well is nent to this work.)• Set CIBP above e: Perforate and ac: Swab test.	directionally drilled, give subsu kisting perforation idize 9532'-9536' (urface locations and measured " s 9570'-9579' (Bou Bough B)	and true vertical (depths for all markers and :	çones pei
proposed work. If well is nent to this work.)• Set CIBP above e: Perforate and ac: Swab test.	directionally drilled, give subsu kisting perforation idize 9532'-9536' (urface locations and measured " s 9570'-9579' (Bou Bough B)	and true vertical (depths for all markers and :	çones "ye:
proposed work. If well is nent to this work.)• Set CIBP above e: Perforate and ac: Swab test.	directionally drilled, give subsu kisting perforation idize 9532'-9536' (urface locations and measured " s 9570'-9579' (Bou Bough B)	and true vertical (depths for all markers and s	tones per
proposed work. If well is nent to this work.)• Set CIBP above e: Perforate and ac: Swab test.	directionally drilled, give subsu kisting perforation idize 9532'-9536' (urface locations and measured " s 9570'-9579' (Bou Bough B)	and true vertical (depths for all markers and s	tones pe
proposed work. If well is nent to this work.)• Set CIBP above e: Perforate and ac: Swab test.	directionally drilled, give subsu kisting perforation idize 9532'-9536' (urface locations and measured " s 9570'-9579' (Bou Bough B)	and true vertical (depths for all markers and s	somes pe
proposed work. If well is nent to this work.)• Set CIBP above e: Perforate and ac: Swab test.	directionally drilled, give subsu kisting perforation idize 9532'-9536' (urface locations and measured " s 9570'-9579' (Bou Bough B)	and true vertical (depths for all markers and s	tones jes
proposed work. If well is nent to this work.)• Set CIBP above e: Perforate and ac: Swab test.	directionally drilled, give subsu kisting perforation idize 9532'-9536' (urface locations and measured " s 9570'-9579' (Bou Bough B)	and true vertical (OF IND A	tones jes
proposed work. If well is nent to this work.)• Set CIBP above e: Perforate and ac: Swab test.	directionally drilled, give subsu kisting perforation idize 9532'-9536' (urface locations and measured " s 9570'-9579' (Bou Bough B)	and true vertical (OF IND A	tones jes
proposed work. If well is nent to this work.)• Set CIBP above e: Perforate and ac: Swab test.	directionally drilled, give subsu kisting perforation idize 9532'-9536' (urface locations and measured " s 9570'-9579' (Bou Bough B)	and true vertical (OF IND A	tones per
set CIBP above en Perforate and ac Swab test. Set up for produc	directionally drilled, give subst kisting perforation idize 9532'-9536' (ction as warranted.	urface locations and measured " s 9570'-9579' (Bou Bough B)	and true vertical (OF IND A	tones jes
Set CIBP above en Perforate and ac: Swab test. Set up for production	directionally drilled, give subst kisting perforation idize 9532'-9536' (action as warranted.	urface locations and measured " s 9570'-9579' (Bou Bough B)	gh C).	OF IND A	993
Set CIBP above en Perforate and ac: Swab test. Set up for produce I hereby certify that the for SIGNED	directionally drilled, give subst kisting perforation idize 9532'-9536' (ction as warranted.	urface locations and measured as 9570'-9579' (Bou Bough B)	gh C).	OCT 26 1	993
proposed work. If well is nent to this work.)• Set CIBP above e: Perforate and ac: Swab test.	directionally drilled, give subst kisting perforation idize 9532'-9536' (ction as warranted. agoing is true and correct tate office use)	urface locations and measured as 9570'-9579' (Bou Bough B)	and true vertical of gh C).	OCT 26 1	993
I hereby certify that the for SIGNED	directionally drilled, give subst kisting perforation idize 9532'-9536' (ction as warranted. agoing is true and correct tate office use)	urface locations and measured is 9570'-9579' (Bou Bough B)	and true vertical of gh C).	OCT 26 1	993
Set CIBP above en Perforate and act Swab test. Set up for produce Set up for produce in hereby certify that the for SIGNED	directionally drilled, give subst kisting perforation idize 9532'-9536' (ction as warranted. sooiling is true and correct tate office use) TI tate office use) TI tate office use) TI	urface locations and measured as 9570'-9579' (Bou Bough B) TILE Petroleum E	and true vertical of gh C). ingineer PETER NOV	OCT 26 1	993

internet (see the second secon

RECEIVED

NOV 0 . 1993

OFFICE