NO. OF COPIES RECEIVED				Free C. Mar		
DISTRIBUTION		NEW MEXICO OIL CONSERVATION COMMISSION			Form C-103 Supersedes Old C-102 and C-103	
ANTA FE	NEWM					
ILE		CONSERVA	TION COMMISSION	Effective 1-1-65		
.S.G.S.				5a. Indicate Type of Lea		
AND OFFICE				State		
PERATOR					Fee	
				5. State Oil & Gas Lease OG-90	∍ No.	
(DO NOT USE THIS FORM	FOR PROPOSALS TO DRILL OR T	REPORTS ON WELL O DEEPEN OR PLUG BACK TO ORM C-101) FOR SUCH PROP(-S A DIFFERENT RESERVOIR.			
OIL GAS WELL	CTHER-			7. Unit Agreement Name	7777777	
Name of Operator Holder Petroleur	8, Farm or Lease Name BA	BA				
Address of Operator	9. Well No.					
Box 1476, Loving	1	1				
	990	North	990	10. Field and Pool, or Wi	ildcat	
Rast	34	7 0			11111	
THE LINE	, SECTION T	0WNSHIP	35-E	мрм. АШШИЙ	111111	
mmmm		ion (Show whether DF, RT			illilli.	
	12. County Roosevelt					
Ch	eck Appropriate Box	To Indicate Nature	of Notice, Report or	Other Data		
NOTICE	OF INTENTION TO:		SUBSEQU	ENT REPORT OF:		
-X						
RFORM REMEDIAL WORK	PLUG	AND ABANDON	AL WORK	ALTERING CASH	NG	
MPORARILY ABANDON		COMMI	ENCE DRILLING OPNS.	PLUG AND ABAND	·	
LL OR ALTER CASING	CHAN	E PLANS CASING	TEST AND CEMENT JOB		JONMENT L	
		отн	1ER_		Г	
OTHER					L	
 Describe Proposed or Comple work) SEE RULE 1103. 	eted Operations (Clearly stat	e all pertinent details, and	give pertinent dates, inclu	ding estimated date of starting o	INV Dropos	
1. Have insta	lled one addition	al 500 BBL stors	op tenk and host	er treater on new t		
pad, and m	oved one 500 BBL.	tank to now ned	Bo tunk and neat	er treater on new t	ank	
,		tank to new pag.				
2. Have made						
	sphilestion to 01.	Conservation C	ommission for pe	rmission to comming	le	
uyurocaroo	na tu mett dole i	rom upper and lo	wer San Andres, a	and if granted, will	1:	
··· ····	our pridge ping a	t 4200°.		J		
	cker and swab zone					
c. Perform	te 4266, 4268, 43	74 4978 4979	4901 4000			

- 4268, 4274, 4276, 4278, 4301, 4302.
- d. Set packer at 4254 and swabe test.
- e. If oil in last swab test, light acid treatment, swab acid back and run pump.
- f. If bottom 3 zones make too much water, run SPDST on zone between 4260 and 4280'. g. If results on SPDST are satisfactory, drop BP at 4290', treat zones 4260-80',
- run pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.								
SIGNED UN ACT	der	President	DATE NOV. 30, 1971					
	Orig. Signed by							
APPROVED BY	Joe D. Ramey Dim. I, Supv.	TITLE	DEG 2 1971					
CONDITIONS OF APPROVAL	, IF ANY:							

· ·

.

•

ELLE VED

DI 11971

OR CONSERVATION LOUGH. HOBESCH. LA