	COPY TO O. C. C.	Budget Bureau No. 42-R358.4. Form Approved,
Form 9-381 a. (Feb. 1951)	(SUBMIT IN TRIPLICATE)	
	(SUBMIT IN TRIPLICATE)	Les C. 062949-A
	DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	Unit
X		· .

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL. NOTICE OF INTENTION TO CHANGE PLANS. NOTICE OF INTENTION TO TEST WATER SHUT-OFF NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL. NOTICE OF INTENTION TO SHOOT OR ACIDIZE NOTICE OF INTENTION TO PULL CASING NOTICE OF INTENTION TO ABANDON WELL.	X	SUBSEQUENT REPORT OF WATER SHUT-OFF
--	---	-------------------------------------

			May 15	, 19_ 63
#1 Ohio-Federal Well No is located	660 ft. f	from 🙀 line	and $\frac{1980}{W}$ ft. from $\left\{\begin{matrix} \mathbf{E} \\ \mathbf{W} \end{matrix}\right\}$ line	e of sec. 26
SW /4 Sec. 26	T-8-5	R-34-E	NMPM	
(14 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	
Undesignated	Roosevelt		New Mexic	
(Field)	(County or Subdivision)		(State or Territ	ory)

The elevation of the derrick floor above sea level is 4256 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-ing points, and all other important proposed work)

Propose to pull casing, plug and abandone well as follows:

- L. Set 20 sack cement plug @ approx. 4734' (PBTD) to 4575' via tubing.
- 2. Load Hole with mud.
- 3. Shoot 4 1/2" casing at 3900' (Expected free point) and pull.
- 4. Shoot & pull \$ 5/8" casing at free point (100% fill would be at approx. 2000')
- 5. Set 40 sack cement plug in top of 8 5/8" stub (50' in pipe and 50' out of pipe) via tubing.
- 6. Set 75 sack coment plug at 450'-350'.
- 7. Set 15 sack cement plug at 25' to surface.
- 8. Weld on appropriate marker.
- 9. Clean up location.

NOTE: Oral permission to plug was given on telephone May 14, 1963 by Mr. Stanley House, New Mexico.

Company Tom Brown Drilling Company, Inc.

Address .	% Albritton & Meyer
	P. O. Box 524
	Midland, Texas

allett Bv

Agent Title