

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

JUL 14 11 59 AM '65

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> WELL GAS <input type="checkbox"/> WELL OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Cactus Drilling Company</b>	8. Farm or Lease Name <b>Bolles</b>
3. Address of Operator <b>Drawer 2068, Hobbs, New Mexico</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>H</b> <b>1980</b> FEET FROM THE <b>N</b> LINE AND <b>660</b> FEET FROM THE <b>E</b> LINE, SECTION <b>20</b> TOWNSHIP <b>8 S</b> RANGE <b>34 E</b> NMPM.	10. Field and Pool, or Wildcat <b>Milnesand, West (S.A.)</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4301 D F</b>	12. County <b>Roosevelt</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well plugging accomplished July 9-11th, 1965 as follows:

Set 15 sx cement plug 4570 covering perforated zone 4560-4554; set 25 sx cement plug 1230' cut-off point, (in and out); set 25 sx cement plug in and out surface casing shoe set at 367'; set 10 sx cement plug at surface. All intervals between cement plugs filled with mud. Lease cleared of all equipment and surface returned to natural contour. Appropriate well marker set identifying the location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Geo. W. Baker TITLE Vice President DATE July 13, 1965

APPROVED BY Leslie V. Clement TITLE Oil & Gas Inspector DATE NOV 10 1965

CONDITIONS OF APPROVAL, IF ANY: