

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)</small>		
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Tom L. Ingram		Wilson
3. Address of Operator		9. Well No.
P. O. Box 1757 - Roswell, New Mexico		1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER M 554 FEET FROM THE South LINE AND 766 FEET FROM THE West LINE, SECTION 29 TOWNSHIP 8-S RANGE 38-E NMPM.		North Sawyer Devonian
11. Elevation (Show whether DF, RT, GR, etc.)		12. County
3966.6 GR		Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Verbal approval obtained from Mr. Joe Ramey April 22, 1965.

Work performed on April 22, 1965 as follows:

Set 100' plug from 11,400 to 11,500. 100' plug 9500-9600, 7400-7500, 5430-5530, 4150-4250. Will cut 8-5/8" and remove approximately 1200'. Will set 100' plug in and out of the stub of the 8-5/8". 50' plug at the base of the surface and 10 sack plug at the surface. Set marker.

The pits will be leveled and the location cleaned up and ready for inspection in approximately 60 days.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Tom L. Ingram TITLE Owner DATE 4-23-65

APPROVED BY Joe Ramey TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: