				- 1 i O 2	Division
	_		1625 N.	French	Dr.
orm 3160- June 1990)		UNITED STATES DEPARTMENT OF THE INTERIO			
		UREAU OF LAND MANAGEMEN			
	-				5. Lease Designation and Serial No.
		Y NOTICES AND REPORTS ON			6. If Indian, Allottee or Tribe Name
Do not u		posals to drill or to deepen or re		reservoir.	
	Use "APPLI	CATION FOR PERMIT-" for su	ch proposals		
<u></u>					7. If Unit or CA, Agreement Designation
SUBMIT IN TRIPLICATE					Todal Lawrence A. Linik Con. 24
1. Type of W	/e#				Todd Lower S A Unit Sec. 31
Off Gas Well Well Other					8. Well Name and No.
2. Name of Operator					<u>-Todd 3103777 5</u>
Saga Petroleum					9. API Well No.
3. Address and Telephone No.					<u>50-04/- (009/</u> 10. Field and Pool, or Exploratory Area
415 W. Wall, Suite 1900, Midland, TX. 79701					Todd Lower San Andres
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 330 FNL & 1650 FWL Sec 31, T7S R 36E					11. County or Parish, State
		E			11. County of Farian, State
					Roosevelt
40		ATE POY(2) TO INDICATE NAT			
12.	CRECK APPROPR	IATE BOX(s) TO INDICATE NAT	UKE OF NOTICE, F	CEPORT, O	
	TYPE OF SUBMISSI	ON	TYPE O	FACTION	
	Notice of Intent	X Abar	donment		Change of Plans
			mpletion		New Construction
	Subsequent Report	Plug	ging Back		Non-Routine Fracturing
		1	ng Repair		Water Shut-Off
	Final Abandonment No	tice 🗌 Alter	ing Casing		Conversion to Injection
		Othe	f		Dispose Water
direction 1. CIBF	ally drilled, give subsurfacy to @ 4234 Dump 20 ce	rations (Cleanly state all pertinet details, and gincations and measured and true vertical depths ment on top. (perfs 4257 to 4302)	ve pertinent dates, including for all markders and zones p	estimated date determinent to this v	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
direction 1. CIBF 2. 100 fi 4. Cut a 5. Spot 6 Spot	atiy drilled, give subsurgey to 2 @ 4234 Dump 20 ce 2 plug @ 2035 - 1935. nd pull 5 1/2 +/- 1000;. 100' plug @ 5 1/2 stub.	Tag oe (50 in 50 out) Bottom of shoe @ 3	ve pertinent dates, including for all markders and zones p AC	estimated date entirent to this v	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is
direction 1. CIBF 2. 100 fl 4. Cut a 5. Spot 6 Spot 7 Surfa 7 Surfa 14. I hereby Signed (This space	ally drilled, give subsurfacy to @ 4234 Dump 20 ce plug @ 2035 - 1935. nd pull 5 1/2 +/- 1000;. 100' plug @ 5 1/2 stub. 100 ft. plug @ 8 5/8 sh ace plug install dry hoe r certify that the foregoing is the for Federal or State office us	rations (Clearly state all pertinet details, and gind cations and measured and true vertical depths ment on top. (perfs 4257 to 4302) 7. Tag oe (50 in 50 out) Bottom of shoe @ 3 narker.	ve pertinent dates, including for all markders and zones p AC	estimated date extinent to this v	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)*
direction 1. CIBF 2. 100 ff 4. Cut a 5. Spot 6 Spot 7., Surfa 7., Surfa 14. I hereby Signed (This space	ally drilled, give subsurfacy to @ 4234 Dump 20 ce plug @ 2035 - 1935. nd pull 5 1/2 +/- 1000;. 100' plug @ 5 1/2 stub. 100 ft. plug @ 8 5/8 sh ace plug install dry hoe r certify that the foregoing is the for Federal or State office us	rations (Cleanly state all pertinet details, and gind cations and measured and true vertical depths ment on top. (perfs 4257 to 4302) 7. Tag oe (50 in 50 out) Bottom of shoe @ 3 narker.	ve pertinent dates, including for all markders and zones p AC	estimated date entirent to this v	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)*
direction 1. CIBF 2. 100 ff 4. Cut a 5. Spot 6 Spot 7., Surfa 7., Surfa 14. I hereby Signed (This space	ally drilled, give subsurface to @ 4234 Dump 20 ce plug @ 2035 - 1935. nd pull 5 1/2 +/- 1000;. 100' plug @ 5 1/2 stub. 100 ft. plug @ 8 5/8 sh nce plug install dry hoe r certify that the foregoing is th for Federal or State office us y	rations (Clearly state all pertinet details, and gind cations and measured and true vertical depths ment on top. (perfs 4257 to 4302) 7. Tag oe (50 in 50 out) Bottom of shoe @ 3 narker.	ve pertinent dates, including for all markders and zones p AC	estimated date entirent to this v	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)*
direction 1. CIBF 2. 100 ff 4. Cut a 5. Spot 6 Spot 7., Surfa 7., Surfa 14. I hereby Signed (This space Approved b Conditions	ally drilled, give subsurfacy to @ 4234 Dump 20 ce plug @ 2035 - 1935. nd pull 5 1/2 +/- 1000;. 100' plug @ 5 1/2 stub. 100 ft. plug @ 8 5/8 sh nce plug install dry hoe r certify that the foregoing is th for Federal or State office us y of approval, if any:	rations (Clearly state all pertinet details, and gind cations and measured and true vertical depths ment on top. (perfs 4257 to 4302) 7. Tag oe (50 in 50 out) Bottom of shoe @ 3 narker.	ve pertinent dates, including for all maricolors and zones p AC 31'. Tag	ertinent to this v	(Hote: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)*

RECEIVED AUG 3 1 2000 BLM ROSWELL, NM