	H TH ON ANTS E	MHONGH		
	N. N. GIL GENE, C			
Form 9–331	P. O. BOX 1983	XICO 88240	Form Approved.	
Dec. 1973	P. O. BOX 1980 HOBBS, NEW ME	VIAA	Budget Bureau No. 42–R1424	
UNITED ST	AIES	5. LEASE	······	
DEPARTMENT OF 1		NM-0145685	LOTTEE OR TRIBE NAME	
GEOLOGICAL	JURVEI			
SUNDRY NOTICES AND		7. UNIT AGREE	MENT NAME	
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9–331–C for such proposals.)				
1. oil gas definition gas well other Injection		Horton Federal		
2. NAME OF OPERATOR	11JEC 6 1011	9. WELL NO.		
Amoco Production Compar	ıy	10. FIELD OR WILDCAT NAME Milnesand San Andres		
3. ADDRESS OF OPERATOR P. O. Box 68, Hobbs,	NM 88240		an Andres M., OR BLK. AND SURVEY OR	
4. LOCATION OF WELL (REPORT LOC		AREA		
below.) AT SURFACE: Sec. 30, T-8	8-S, R-35-E, Unit J	<u>30-8-35</u> 12. COUNTY OR	PARISH 13. STATE	
AT TOP PROD. INTERVAL: 2310 AT TOTAL DEPTH:) FSL X 2246' FEL	Roosevelt		
16. CHECK APPROPRIATE BOX TO I	NDICATE NATURE OF NOTICE	14. API NO.		
REPORT, OR OTHER DATA			5. ELEVATIONS (SHOW DF, KDB, AND WD)	
REQUEST FOR APPROVAL TO: SUBSEQUENT BEPORT OF		4224 RDB	· · · · · · · · · · · · · · · · · · ·	
TEST WATER SHUT-OFF		、亚国川		
FRACTURE TREAT		1001		
REPAIR WELL	日 <u>此</u> AUG 24	Change on	ults of multiple completion or zone Form 9-330.)	
MULTIPLE COMPLETE		343		
ABANDON* Convert to inio	tion U.S. GEOLOGIA	UAL BURVET VV MEXICO	an a	
· · · · · · · · · · · · · · · · · · ·			ile and give	
17. DESCRIBE PROPOSED OR COMPL including estimated date of startin measured and true vertical depths	og anv proposed work. If well is di	rectionally drilled.	give subsurface locations and	
		-		
Propose to convert to	injection by the follow	ing method:		
Pull production equipme	ent. Tag bottom and cl	ean out to 4	764'. Run	
	ker at 4570'. Acidize	with 2000 ga	IS. OT 15%	
workstring and set pac	MUCOL A in 2 atagaa	I LUND WILLE	frach water	
workstring and set pach NEFE acid and 200 gals Pull workstring and tre	. MUSOL-A in 2 stages. eating packer. Run 2-3	/8" plastic	fresh water.	
workstring and set pach NEFE acid and 200 gals Pull workstring and tre	. MUSOL-A in 2 stages. eating packer. Run 2-3 Place well on injection	/8" plastic	fresh water.	
workstring and set pach NEFE acid and 200 gals Pull workstring and tre	. MUSOL-A in 2 stages. eating packer. Run 2-3	/8" plastic	fresh water.	
workstring and set pac NEFE acid and 200 gals Pull workstring and tro and packer to 4550'. I	. MUSOL-A in 2 stages. eating packer. Run 2-3 Place well on injection	/8" plastic	fresh water.	
workstring and set pach NEFE acid and 200 gals Pull workstring and tre	. MUSOL-A in 2 stages. eating packer. Run 2-3 Place well on injection	/8" plastic	fresh water.	
workstring and set pac NEFE acid and 200 gals Pull workstring and tro and packer to 4550'. I	. MUSOL-A in 2 stages. eating packer. Run 2-3 Place well on injection 	/8" plastic •	fresh water.	
workstring and set pack NEFE acid and 200 gals Pull workstring and tro and packer to 4550'. I O+4-USGS, R 1-Hou	. MUSOL-A in 2 stages. eating packer. Run 2-3 Place well on injection 	/8" plastic •	tresh water. coated tubing	
<pre>workstring and set pack NEFE acid and 200 gals Pull workstring and tro and packer to 4550'. I 0+4-USGS, R 1-Hou Subsurface Safety Valve: Manu. and Ty 18. Thereby certify that the topegoing</pre>	. MUSOL-A in 2 stages. eating packer. Run 2-3 Place well on injection 	/8" plastic •	tresh water. coated tubing Set @Ft.	
<pre>workstring and set pack NEFE acid and 200 gals Pull workstring and tro and packer to 4550'. I 0+4-USGS, R 1-Hou Subsurface Safety Valve: Manu. and Ty 18. Thereby certify that the topegoing</pre>	. MUSOL-A in 2 stages. eating packer. Run 2-3 Place well on injection 1-Susp 1-GPM pe	/8" plastic • 	tresh water. coated tubing Set @Ft.	
workstring and set pack NEFE acid and 200 gals Pull workstring and tro and packer to 4550'. I O+4-USGS, R 1-Hou Subsurface Safety Valve: Manu. and Ty 18. Thereby certify that the opegoing SIGNED	. MUSOL-A in 2 stages. eating packer. Run 2-3 Place well on injection 1-Susp 1-GPM he triff and correct HTLE Admin. Analys (This space for Federal or State offi	/8" plastic • • • • • •	fresh water. coated tubing Set @Ft. 8-21-81	
workstring and set pack NEFE acid and 200 gals Pull workstring and tro and packer to 4550'. I 0+4-USGS, R 1-Hou Subsurface Safety Valve: Manu. and Ty 18. Thereby certify that the topegoing SIGNED	. MUSOL-A in 2 stages. eating packer. Run 2-3 Place well on injection 1-Susp 1-GPM he trafang correct ITLE Admin. Analys (This space for Federal or State offi	/8" plastic • • • • • •	fresh water. coated tubing Set @Ft. 8-21-81	

1

۰.

٠

