	M OF CNS. COMMISSION
	Drawer Uns. Commission
AND MANAGE	Artesia, NM 88210
Form 9-331 Dec. 1973 UNITED STATES AFFFFFFFFF DEPARTMENT OF THEINTERIOR 8 1983	Form Approved. Budget Bureau No. 42-R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR 3 1983 GEOLOGICAL SURVEY JUL 28 1983	NM-0145685
	6. IF INDIAN, ALLOTTEE CR TRIBE NAME
SUNDRY NOTICES AND REPORTS DON WELLS (Do not use this form for proposals to drill or to deepen plug back to additent reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME
	8. FARM OR LEASE NAME Horton Federal
1. oil gas other	9. WELL NO.
2. NAME OF OPERATOR Amoco Production Company	5
3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Milnesand San Andres
P. O. Box 68, Hobbs, New Mexico 88240	11. SEC., T., R., M., OR BLK. AND SURVEY OR
 LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 	AREA 30-8-35
AT SURFACE: 1650' FNL X 2244' FEL Sec. 30 AT TOP PROD. INTERVAL: Unit G, SW/4,NE/4	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	Roosevelt NM
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	4686' RDB
FRACTURE TREAT	ED SY
SHOOT OR ACIDIZE	
PULL OR ALTER CASING AUG 23	19803E: Report results of multiple completion or zone change on Form 9-333.)
MULTIPLE COMPLETE	. D.
ABANDON*	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	
Propose to clean out fill and acidize as follows:	
Rig up service unit, pull rods, pump and tubing. Run workstring with bit and clean out fill to 4738'. Sample and analyze cutting. Pull workstring and bit.	
Run in hole with 2-7/8" workstring as follows:	
a) Run 1 joint of 2-7/8" tubing below packer.	
b) Run treating packer. c) Run 2-7/8" tubing to surface.	
d) land tailpipe near TD (4738')	
 e) Spot 275 gals of Visco 4948' mixed with 546 gals of water from 4738' to 4000' f) Pull up workstring and set packer at 4550'. 	
* Shut down operations at least 12 hours to allow scale converter to work.	
Run log from 4730' to 4550'. Tag with radioa	ctive material and acidize down
0+4-BLM, R 1-HOU, R.E.Ogden, Rm 21.150 1-	
Subsurface Safety Valve: Manu. and Type Ft. 18. Thereby certify that the foregoing is true and correct	
signed Title_Ast. Adm. Analyst_DATE7-25-83	
4This space for Federal or State office use)	
APPROVED BY TITLE DATE DATE	
For Switzer 19 1 1	DATE
AUG 22 1983	
*See Instructions on Reverse Side	

tubing, with 7500 gals \uparrow 15% LSTNE HCL acid containing gal/1000 corrosion inhibitor. Stag as follows:

a) Pump 2500 gal of 15% LSTNE HCL acid.

b) Pump block consisting of 300# graded rock salt and 100# mesh salt in 300 gals of 30# gelled brine.

c) Repeat step A & B two more times and flush with fresh water.

Run after treatment log from 4730'-4550'. Release packer, pull tubing, packer and tailpipe. Run in hole with 2-7/8" tubing with seating nipple on bottom. Land sand at 4685'. Return well to production. Scale squeeze procedure:

Produce well to recover load prior to scale squeeze. Pump 15 barrels produced water pad down casing to displace any oil present in annhlus. Pump down casing 2 drums Visco 953 mixed in 27 bbls of fresh water. Flush and overflush down casing with 275 bbls. Shut in well for 24 hours to allow scale inhibitor to absorb.

RECEIVED

AUG 29 1983 O.C.D. HOB25 OFFICE