Form 9-331 Dec. 1973 UNITED STATES	Budget Bureau No. 42R1424				
UNITED STATES HOBBE, REW MEXIC DEPARTMENT OF THE INTERIOR	NM-0145685				
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME				
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME				
(Dc not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME				
1. oil gas	Horton Federal				
well 🗀 well 🗀 other Injection	9. WELL NO.				
2. NAME OF OPERATOR	7				
Amoco Production Company	10. FIELD OR WILDCAT NAME				
3. ADDRESS OF OPERATOR	Milnesand-San Andres				
P. O. Box 68, Hobbs, NM 88240	11. SEC., T., R., M., OR BLK. AND SURVEY OR				
<ol> <li>LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)</li> </ol>	AREA AREA				
AT SURFACE:	30-8-35 12. COUNTY OR PARISH 13. STATE				
AT TOP PROD. INTERVAL:					
AT TOTAL DEPTH: 330' N + 2241 /E	RooseveltNM				
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,					
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)				
	4227' RDB				
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:					
FRACTURE TREAT					
REPAIR WELL	1 (NOTE: Peoplet insulting of multiple and bits				
PULL OR ALTER CASING	1 (NOTE: Report results of multiple completion or zone change on Form 9–330.)				
MULTIPLE COMPLETE	8 <b>C</b> 1 S				
	OL & GAS U S. GEOLOGICAL SURVEY				
	NEW MERICO				
<ol> <li>DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinent</li> </ol>	rectionally drilled, give subsurface locations and				

ġ

1

Propose to convert to injection by the following method:

. . . \*

. . . . .

Pull production equipment. Tag bottom to 4732'. Run packer and spot control valve. Set packer at 4540'. Displace 5 bbl. C-Dex into fromation. Shear spot valve. Swab back and pull tubing and packer. Run workstring to 4570' and set packer at 4540'. Acidize with 3000 gals. 15% and 300 gals. MUSOL-A in 2 stages. Flush with fresh water. Pull workstring and treating packer. Run 2-3/8" plastic coated tubing with packer set at 4550'. Place well on injection.

0+4-USGS, R	1-Hou	1-Susp	1-GPM			
Subsurface Safety Valve: Ma	anu. and Type	×			Set @	Ft.
18. I hereby gerify that the	presoing is t	his And confect				
SIGNED Jug	1 (ll	CULLE Ad	min. Analyst	DATE	8-21-81	
		(This space for F	ederal or State office	use)	PPROVED	1
APPROVED BY		TITLE		DATE		
CONDITIONS OF APPROVAL, I	F ANY:	SUBJECT 1				
		APPROVAL	BY STATE	A	UG 2 7 1981	•
		*See Instruc	tions on Reverse Sid	1º 200	AES A. GILLHAM RICT SUPERVISOR	