COPY TO O C C

Form 9-331		IIIII O OTATEO					
(May 1963)	DEDART	UNI D STATES	SUBMIT IN TRIPLICATION OF	E* Form appro Budget Bur	ved. eau No. 42-R1424.		
		MENT OF THE INTERIO	IOR verse side)	5. LEASE DESIGNATION	N AND SERIAL NO.		
		GEOLOGICAL SURVEY		Milnesand Un	it LC060978		
(Do not use	SUNDRY NOT this form for propo Use "APPLIC.	6. IF INDIAN, ALLOTT	EE OR TRIBE NAME				
1.							
WELL X 6.1	AS OTHER	7. UNIT AGREEMENT N	AME				
2. NAME OF OLERAT	- Ollien	Milnesand	Milnesand Unit				
				8. FARM OR LEASE NA	ME		
3. ADDRESS OF OPE	AS PETROLLJM	Jacobs Fed					
				9. WELL NO.	<del>crai</del>		
1300 Wilco	o Building, N	Midland, Texas 79701		0.6			
4. LOCATION OF WE: See also space 1			26 10. FIELD AND POOL, OR WILDCAT				
At surface	,		i e				
				Milnesand (S			
		11. SEC., T., R., M., OR SURVEY OF ARE,	11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA				
Unit Letter	ר <sup>ווקון</sup> ההחו	'SL & 660' FEL					
14. PERMIT NO.	- 1 , 000 I	Sec. 19, T-8-	S, R-35-E				
חביים מ		15. ELEVATIONS (Show whether DF,	RT, GR, etc.)	12. COUNTY OR PARISE	I 13. STATE		
R-3.770		4220' GL		Roosevelt	New Mexico		
16.	Check Ap	propriate Box To Indicate No	ature of Notice Report as	Oshar Data			
	NOTICE OF INTENT	TION TO		Omer Data			
	OF INIEM.	10.1 10.	SUEST	COHENT PEROPE ON.			

NOTICE OF INTENTION TO:					SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF		PULL OR ALTER CASING				<u></u>	
FRACTURE TREAT					WATER SHUT-OFF	<u> </u>	REPAIRING WELL
SHOOT OR ACIDIZE		MULTIPLE COMPLETE		l	FRACTURE TREATMENT		ALTERING CASING
		ABANDON*		l	SHOOTING OR ACIDIZING		ABANDONMENT*
REPAIR WELL		CHANGE PLANS			(Other)		
(Other) Convert	To	Injection Well	X		(Note: Report resu	ılts o	f multiple completion on Well
L'OODIDI SECONO					Completion or Recor	mplet	ion Report and Log form

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Pull 2 3/8" tubing, inspect and plastic coat internally.
 Run plastic coated tubing w/Injection Packer set @ approximately 4500'.

3. Treat injection zone w/approximately 1000 Gal. clean sweep.

4. Place on water injection.

18. I hereby certify that the foregoing is true and correct	
SIGNED MANNY	TITLE District Oper. Supt. Western DATE July 19, 1971
(This space for Federal or State office use)	
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE ADDROVED DATES
of Milkotal, is Ani:	OE Instructions on Reverse Signatur R. BROWN DISTRICT ENGINEER
*\$	ee Instructions on Reverse Signatur R. BROWN  DISTRICT ENGINEER

## RECEIVED

JUL 27 1971

OIL CONSERVATION COMM. Hodes, H. M.