	N. M TL COM3. COMMISSION	
	P. O. DOX 1989	
	HOBBS, NEW MEXICO 88240	
	Form 9-331 110 D.D.C., 11211 1121100 0.0.0.0	Form Approved.
	UNITED STATES	Budget Bureau No. 47-R1424 5. LEASE
•	DEPARTMENT OF THE INTERIOR	NM-0145685
	GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
	*(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
	1. oil gas	Horton Federal
	well well other	9. WELL NO.
	2. NAME OF OPERATOR	8
-	AMOCO PRODUCTION COMPANY	10. FIELD OR WILDCAT NAME
	3. ADDRESS OF OPERATOR PL 0. Box 68, Hobbs, NM 88240	Milnesand San Andres
	P. O. Box 68, Hobbs, NM 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
	below.)	
	AT SURFACE: 2310' FSL X 1650' FWL	12. COUNTY OR PARISH 13. STATE
	AT TOP PROD. INTERVAL Unit K, NE/4, SW/4) AT TOTAL DEPTH:	Roosevelt NM
· -		14. API NO.
	16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
	REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	4228' RDB
	TEST WATER SHUT-OFF	
	FRACTURE TREAT	
	SHOOT OR ACIDIZE 🔀 🗌	6 <u></u> c
	PULL OR ALTER CASING	(NOTE: Report results of multiple ampletion or zone change on Form 9-330.)
	CHANGE ZONES	
	(other)	Str.
	 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d 	te all pertinent details, and give pertinent dates,
	measured and true vertical depths for all markers and zones pertiner	nt to this work.)*
	Propose to run casing inspection log with cali	· · · · · · · · · · · · · · · · · · ·
	Tropose to run casing inspection roy with car	iper, pipe recovery log,
	raise cement behind 4-1/2" casing, perforate a	
	raise cement behind 4-1/2" casing, perforate a per the following:	additional pay and acidize
	raise cement behind 4-1/2" casing, perforate a per the following: Move in service unit and pull rods, pump, and	additional pay and acidize tubing. RIH with RBP and
	raise cement behind 4-1/2" casing, perforate a per the following: Move in service unit and pull rods, pump, and tubing. Set RBP at ±4640'. Pressure test and	additional pay and acidize tubing. RIH with RBP and d cap with 10' of sand.
	raise cement behind 4-1/2" casing, perforate a per the following: Move in service unit and pull rods, pump, and tubing. Set RBP at ±4640'. Pressure test and Pressume test 4-1/2" casing to 500 psi. Run ca	additional pay and acidize tubing. RIH with RBP and d cap with 10' of sand. asing inspection log with
	raise cement behind 4-1/2" casing, perforate a per the following: Move in service unit and pull rods, pump, and tubing. Set RBP at ±4640'. Pressure test and Pressume test 4-1/2" casing to 500 psi. Run ca caliper from 4640' to surface. Run pipe recov	additional pay and acidize tubing. RIH with RBP and cap with 10' of sand. asing inspection log with very log. Run in hole with
, ,	raise cement behind 4-1/2" casing, perforate a per the following: Move in service unit and pull rods, pump, and tubing. Set RBP at ±4640'. Pressure test and Pressum test 4-1/2" casing to 500 psi. Run ca caliper from 4640' to surface. Run pipe recov casing gun and perforate apx.5' above free poi	additional pay and acidize tubing. RIH with RBP and d cap with 10' of sand. asing inspection log with very log. Run in hole with int with 4 DPJSPF. POH.
۰. ۲	raise cement behind 4-1/2" casing, perforate a per the following: Move in service unit and pull rods, pump, and tubing. Set RBP at ±4640'. Pressure test and Pressume test 4-1/2" casing to 500 psi. Run ca caliper from 4640' to surface. Run pipe recov casing gun and perforate apx.5' above free poi Attempt to establish circulation around 4-1/2"	additional pay and acidize tubing. RIH with RBP and d cap with 10' of sand. asing inspection log with very log. Run in hole with int with 4 DPJSPF. POH. ' casing by pumping pro-
• •	raise cement behind 4-1/2" casing, perforate a per the following: Move in service unit and pull rods, pump, and tubing. Set RBP at ±4640'. Pressure test and Pressum test 4-1/2" casing to 500 psi. Run ca caliper from 4640' to surface. Run pipe recov casing gun and perforate apx.5' above free poi	additional pay and acidize tubing. RIH with RBP and d cap with 10' of sand. asing inspection log with very log. Run in hole with int with 4 DPJSPF. POH. ' casing by pumping pro- te cement behind casing,
• •	raise cement behind 4-1/2" casing, perforate a per the following: Move in service unit and pull rods, pump, and tubing. Set RBP at ±4640'. Pressure test and Pressumetest 4-1/2" casing to 500 psi. Run ca caliper from 4640' to surface. Run pipe recov casing gun and perforate apx.5' above free poi Attempt to establish circulation around 4-1/2" duced water. A supplemental brief to circulat	additional pay and acidize tubing. RIH with RBP and d cap with 10' of sand. asing inspection log with very log. Run in hole with int with 4 DPJSPF. POH. ' casing by pumping pro- te cement behind casing,
· · · ·	raise cement behind 4-1/2" casing, perforate a per the following: Move in service unit and pull rods, pump, and tubing. Set RBP at ±4640'. Pressure test and Pressure test 4-1/2" casing to 500 psi. Run ca caliper from 4640' to surface. Run pipe recov casing gun and perforate apx.5' above free poi Attempt to establish circulation around 4-1/2" duced water. A supplemental brief to circulat perforate additional pay, and acidize will be of the above.	additional pay and acidize tubing. RIH with RBP and d cap with 10' of sand. asing inspection log with very log. Run in hole with int with 4 DPJSPF. POH. ' casing by pumping pro- te cement behind casing, issued based on the results
۰ ۰	 raise cement behind 4-1/2" casing, perforate a per the following: Move in service unit and pull rods, pump, and tubing. Set RBP at ±4640'. Pressure test and Pressure test 4-1/2" casing to 500 psi. Run ca caliper from 4640' to surface. Run pipe recover casing gun and perforate apx.5' above free point Attempt to establish circulation around 4-1/2" duced water. A supplemental brief to circulate perforate additional pay, and acidize will be of the above. Subject and perform Rand Typogden, HOU Rm. 21.150- 	additional pay and acidize tubing. RIH with RBP and d cap with 10' of sand. asing inspection log with very log. Run in hole with int with 4 DPJSPF. POH. ' casing by pumping pro- te cement behind casing, issued based on the results
	 raise cement behind 4-1/2" casing, perforate a per the following: Move in service unit and pull rods, pump, and tubing. Set RBP at ±4640'. Pressure test and Pressure test 4-1/2" casing to 500 psi. Run ca caliper from 4640' to surface. Run pipe recover casing gun and perforate apx.5' above free point Attempt to establish circulation around 4-1/2" duced water. A supplemental brief to circulate perforate additional pay, and acidize will be of the above. Subsurface Safety Valve: ManuRand Typogden, HOU Rm. 21.150-18. Thereby approximation is true and correct 	additional pay and acidize tubing. RIH with RBP and d cap with 10' of sand. asing inspection log with very log. Run in hole with int with 4 DPJSPF. POH. ' casing by pumping pro- te cement behind casing, issued based on the results
• • •	 raise cement behind 4-1/2" casing, perforate a per the following: Move in service unit and pull rods, pump, and tubing. Set RBP at ±4640'. Pressure test and Pressure test 4-1/2" casing to 500 psi. Run ca caliper from 4640' to surface. Run pipe recover casing gun and perforate apx.5' above free point Attempt to establish circulation around 4-1/2" duced water. A supplemental brief to circulate perforate additional pay, and acidize will be of the above. Subject and perform Rand Typogden, HOU Rm. 21.150- 	additional pay and acidize tubing. RIH with RBP and d cap with 10' of sand. asing inspection log with very log. Run in hole with int with 4 DPJSPF. POH. ' casing by pumping pro- te cement behind casing, issued based on the results
	 raise cement behind 4-1/2" casing, perforate a per the following: Move in service unit and pull rods, pump, and tubing. Set RBP at ±4640'. Pressure test and Pressure test 4-1/2" casing to 500 psi. Run ca caliper from 4640' to surface. Run pipe recover casing gun and perforate apx.5' above free point Attempt to establish circulation around 4-1/2" duced water. A supplemental brief to circulate perforate additional pay, and acidize will be of the above. Subsurface Safety Valve: ManuRand Typogden, HOU Rm. 21.150-18. I hereby acting that the foregoing is true and correct 	additional pay and acidize tubing. RIH with RBP and d cap with 10' of sand. asing inspection log with very log. Run in hole with int with 4 DPJSPF. POH. ' casing by pumping pro- te cement behind casing, issued based on the results
	 raise cement behind 4-1/2" casing, perforate a per the following: Move in service unit and pull rods, pump, and tubing. Set RBP at ±4640'. Pressure test and Pressure test 4-1/2" casing to 500 psi. Run ca caliper from 4640' to surface. Run pipe recover casing gun and perforate apx.5' above free point Attempt to establish circulation around 4-1/2" duced water. A supplemental brief to circulate perforate additional pay, and acidize will be of the above. Subsurface Safety Valve: ManuRandETypogden, HOU Rm. 21.150-11-CMH 18. Thereby achieve the foregoing is true and correct signed for the foregoing	additional pay and acidize tubing. RIH with RBP and d cap with 10' of sand. asing inspection log with very log. Run in hole with int with 4 DPJSPF. POH. ' casing by pumping pro- te cement behind casing, issued based on the results
	<pre>raise cement behind 4-1/2" casing, perforate a per the following: Move in service unit and pull rods, pump, and tubing. Set RBP at ±4640'. Pressure test and Pressure test 4-1/2" casing to 500 psi. Run ca caliper from 4640' to surface. Run pipe recov casing gun and perforate apx.5' above free poi Attempt to establish circulation around 4-1/2" duced water. A supplemental brief to circulat perforate additional pay, and acidize will be of the above. Subsurface Safety Valve: ManuRand TypOgden, HOU Rm. 21.150- 18. Thereby aerity that the foregoing is true and correct signed for the above. Approved BY CONDITIONS OF APPROVAL, IF ANY: </pre>	additional pay and acidize tubing. RIH with RBP and d cap with 10' of sand. asing inspection log with very log. Run in hole with int with 4 DPJSPF. POH. ' casing by pumping pro- te cement behind casing, issued based on the results
۰ ۰	<pre>raise cement behind 4-1/2" casing, perforate a per the following: Move in service unit and pull rods, pump, and tubing. Set RBP at ±4640'. Pressure test and Pressure test 4-1/2" casing to 500 psi. Run ca caliper from 4640' to surface. Run pipe recov casing gun and perforate apx.5' above free poi Attempt to establish circulation around 4-1/2" duced water. A supplemental brief to circulat perforate additional pay, and acidize will be of the above. Subsurface Safety Valve: ManuRand TypOgden, HOU Rm. 21.150- 18. Thereby aerity that the foregoing is true and correct signed for the above. Approved BY CONDITIONS OF APPROVAL, IF ANY: </pre>	additional pay and acidize tubing. RIH with RBP and d cap with 10' of sand. asing inspection log with very log. Run in hole with int with 4 DPJSPF. POH. ' casing by pumping pro- te cement behind casing, issued based on the results
· · · · · · · · · · · · · · · · · · ·	 raise cement behind 4-1/2" casing, perforate a per the following: Move in service unit and pull rods, pump, and tubing. Set RBP at ±4640'. Pressure test and Pressure test 4-1/2" casing to 500 psi. Run ca caliper from 4640' to surface. Run pipe recover casing gun and perforate apx.5' above free point Attempt to establish circulation around 4-1/2" duced water. A supplemental brief to circulat perforate additional pay, and acidize will be of the above. Subsurface Safety Valve: ManuRandETypogden, HOU Rm. 21.150-118. I hereby performing that the foregoing is true and correct Subsurface Safety Valve: ManuRandETypogden, HOU Rm. 21.150-118. I hereby performing that the foregoing is true and correct Subsurface Safety Valve: ManuRandETypogden, HOU Rm. 21.150-118. I hereby performing that the foregoing is true and correct Subsurface Safety Valve: ManuRandETypogden, HOU Rm. 21.150-118. I hereby performing that the foregoing is true and correct Subsurface Safety Valve: ManuRandETypogden, HOU Rm. 21.150-118. I hereby performing that the foregoing is true and correct Subsurface Safety Valve: ManuRandETypogden, HOU Rm. 21.150-118. I hereby performing that the foregoing is true and correct Subsurface Safety Partice Provide Partice Partice	additional pay and acidize tubing. RIH with RBP and d cap with 10' of sand. asing inspection log with very log. Run in hole with int with 4 DPJSPF. POH. ' casing by pumping pro- te cement behind casing, issued based on the results
•	<pre>raise cement behind 4-1/2" casing, perforate a per the following: Move in service unit and pull rods, pump, and tubing. Set RBP at ±4640'. Pressure test and Pressure test 4-1/2" casing to 500 psi. Run ca caliper from 4640' to surface. Run pipe recov casing gun and perforate apx.5' above free poi Attempt to establish circulation around 4-1/2" duced water. A supplemental brief to circulat perforate additional pay, and acidize will be of the above. Subsurface Safety Valve: ManuRand TypOgden, HOU Rm. 21.150- 18. Thereby aerity that the foregoing is true and correct signed for the above. Approved BY CONDITIONS OF APPROVAL, IF ANY: </pre>	additional pay and acidize tubing. RIH with RBP and d cap with 10' of sand. asing inspection log with very log. Run in hole with int with 4 DPJSPF. POH. ' casing by pumping pro- te cement behind casing, issued based on the results