o Appropriate District Office		of New Mexico Natural Resources Depa	rtment		Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	P.(VATION DIVIS D. Box 2088	V	VELL API NO.	
DISTRICT II 2.0. Drawer DD, Artesia, NM 88210	Santa Fe, Nev	v Mexico 87504-2088		5. Indicate Type of Leas	STATE X FEE
DISTRICT III 000 Rio Brazos Rd., Aztec, NM 87410			F	6. State Oil & Gas Lease	е No. К-3935
(DO NOT USE THIS FORM FOR PE DIFFERENT RESE	TICES AND REPORT ROPOSALS TO DRILL OR ERVOIR. USE "APPLICATI C-101) FOR SUCH PROPC	to deepen or plug bac on for permit"		7. Lease Name or Unit A	Agreement Name
. Type of Well: OIL GAS WELL X WELL				Haley Chaveı Sec. 34	roo San Andres
Name of Operator		•		8. Well No.	
Murphy Operating Co	orporation		·	<u>3-y</u>	
 Address of Operator P. O. Drawer 2648, 	Roswell, New Me	vico 88202-2648		9. Pool name of Wildcal Chaveroo Sa	-
Well Location	nosherry neu ne.		I,		
Unit Letter : 6	60 Feet From The N	orth Line and	1880	Feet From The	West
Section 34		outh Range 33 E		MPM Roose	velt Coum
	10. Elevation (.	Show whether DF, RKB, RT, G	K, etc.)		
1. Check	Appropriate Box to	Indicate Nature of N	otice Rer	Nort or Other Dat	//////////////////////////////////////
	ITENTION TO:			EQUENT REP	
			0000	<u></u>	
	PLUG AND ABANE		NORK		ERING CASING
	CHANGE PLANS		DRILLING C	opns. 🛄 Plu	G AND ABANDONMEN
ULL OR ALTER CASING		CASING TES			
THER:					
 THER:	rations (Clearly state all perti		dates, includir	sg estimated date of start	ing any proposed
12. Describe Proposed or Completed Ope work) SEE RULE 1103. 11-30-89 TOH with to split ca 12-5-89 Test cas	rods, pump and sing @ 4380' and ing to 2000 psig t well. TOH. TI	ent details, and give pertinent	ı casing 1980'. with bi	inspection 1 TIH and set t and casing	og. Found RBP @ 4150'. scrapper.
12-5-89 Completed Operation 12-5-89 Completed Operation 2010 Completed 2010 Completed	rods, pump and sing @ 4380' and ing to 2000 psig t well. TOH. TI on.	tubing. TOH with possible hole @ . Held ok. TIH H with rods, pum	n casing 1980'. with bi p and tu	inspection 1 TIH and set t and casing bing. Return	og. Found RBP @ 4150'. scrapper. well to
12. Describe Proposed or Completed Ope work) SEE RULE 1103. 11-30-89 TOH with to split ca 12-5-89 Test cas Clean ou producti I hereby certify that the information above in SIGNATURE	rods, pump and sing @ 4380' and ing to 2000 psig t well. TOH. TI on.	tubing. TOH with possible hole @ . Held ok. TIH H with rods, pum	n casing 1980'. with bi p and tu	inspection 1 TIH and set t and casing bing. Return	og. Found RBP @ 4150'. scrapper. well to
12. Describe Proposed or Completed Ope work) SEE RULE 1103. 11-30-89 TOH with to split ca 12-5-89 Test cas Clean ou producti I hereby certify that the information above in SIGNATURE TYPE OR PRINT NAME Brown	rods, pump and sing @ 4380' and ing to 2000 psig t well. TOH. TI on.	tubing. TOH with possible hole @ . Held ok. TIH H with rods, pum	n casing 1980'. with bi p and tu	inspection 1 TIH and set t and casing bing. Return	og. Found RBP @ 4150'. scrapper. well to