## SUBMIT IN TRIF TATE INTED STATES

Form approved.

May 1963)	DEPARTML . COF THE INTER	Other instruction re-	5. LEASE DESIGNATION A	No. 42-R1424. ND SERIAL NO.						
DEPARTMEI OF THE IN		IOI verse side)	NM-044701-C							
			6. IF INDIAN, ALLOTTEE OR TRIBE NAME							
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)										
			7. UNIT AGREEMENT NAME							
OIL GAS WELL OTHER										
. NAME OF OPERATOR			8. FARM OR LEASE NAME							
GEROR OIL LTD., 1962  B. ADDRESS OF OPERATOR  1815 RAST BROADWAY, TUBCOM, ARIZONA 85719			Royal 9. WELL NO. #3							
						i. Location of well (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface			10. FIELD AND POOL, OR WILDCAT	
									Cheveroo	
			11. SEC., T., E., M., OR BL SURVEY OR AREA	AND						
1980 FSL & 1980 FBL  14. PERMIT NO.   15. ELEVATIONS (Show whether DF, RT, GR, etc.)			19-7-33							
			12. COUNTY OR PARISH   13. STATE							
. PERMIT NO.	16. ELEVATIONS (Show whether I		Roosevelt	N. M.						
	1137 VA		, MOODOTOLO							
•	Check Appropriate Box To Indicate	Nature of Notice, Report, or C	Other Data							
NO	TICE OF INTENTION TO:	SUBSEQU	ENT REPORT OF:							
			REPAIRING W	INI.T.						
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF FRACTURE TREATMENT	ALTERING CAS							
FRACTURE TREAT	MULTIPLE COMPLETE	SHOOTING OR ACIDIZING	ABANDON MEN							
SHOOT OR ACIDIZE	ABANDON* CHANGE PLANS	(Other)								
REPAIR WELL	CHANGE FLANS	(Norg: Report results	of multiple completion of letion Report and Log form	n Well						
(Other)	OMPLETED OPERATIONS (Clearly state all pertine	out details and size partinent dates	including estimated date	of starting an						
proposed work. If w	ompleted operations (Clearly state an perting vell is directionally drilled, give subsurface locally drilled, give subsurface locally drilled.	cations and measured and true vertice	al depuhs for all markers	and zones pert						
Mens of this worm,										
			1,34							
Spot a 100"	plug to cover all peri	crations.	<u></u> . ,							
Lord bole w	/mud-laden fluids.		1.144	en e						
Pull approximately 3,000' of production casing.										
Snot a 100'	plug across casing stu	b.								
Spot a 100'	plug in and out of the	bese of surface of	asing.	•						
Spot a 10 w	x plug in top of hole	ind erect a 4" regu	lation marke	r.						
	•									
AMENDMENT:			<u> </u>							
A STATE OF THE PARTY OF THE PAR	- ·									
Coment plus	over perforations should b	e a minimum of 25 sact	is.							
	ional 100' cement plug in i									
	470									
	The state of the s									
	Mark Control of the C									
	10. 第二十二 13. 第二 1 · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·							

Jan. 8, 1973 AGENT DATE .. (This space for Federal or State office use) TITLE .

\*See Instructions on Reverse Sid

RECEIVED

JAN 1 gra

Con Control Marine Table