	IDRY NOTICES	AND REPORTS	ON WELLS		N.M. 055 F INDIAN, ALLO	TTEE OR TR
(Do not use this	form for propesals to d Use "APPLICATION F	irill or to deepen or plug FOR PERMIT" for such	g back to a different reservoir proposals.)	r.		
1. OIL GAS WELL X WELL	OTHER			7. 0	NIT AGREEMENT	T NAME
2. NAME OF OPERATOR			<u> </u>	8. F	ARM OR LEASE	NAME
Champlin Pet	roleum Company	r			Lauck-Fe	deral
		Town 70701		9. w	ELL NO.	•
<ul> <li>701 Wilco Bldg., Midland, Texas 79701</li> <li>4. LOCATION OF WELL (Report location dearly and in accordance with any State requirements.* See also space 17 below.) At surface</li> </ul>					6 FIELD AND POOL	L, OR WILDC
1980' FNL & 1980' FEL, Sec. 29, T-7-S, R-33-E, Unit Letter G					Chaveroo-San An 11. sec., T., B., M., OB BLK. AND SUBVEY OF AREA	
14. PERMIT NO.					с. 29, Т	
14. PERMIT NU.	15. EL	LEVATIONS (Show whether 4434 DF	DF, RT, GR, etc.)		COUNTY OR PAR	New
16.	Check Approprie	ate Box To Indicate	Nature of Notice, Repo			
1	NOTICE OF INTESTION TO :			SUBSEQUENT B	•	
TEST WATER SHUT-O	FF PULL OR	ALTER CASING	WATER SHUT-OFF		REPAIRIN	G WELL
FRACTURE TREAT		S COMPLETE	FRACTURE TREATMEN	i <b>r</b>	ALTERING	G CASING
SHOOT OR ACIDIZE	ABANDON		SHOOTING OR ACIDIZI		ABANDON	MENT*
REPAIR WELL (Other)	CHANGE I	PLANS	(Other)	results of mu	tiple completi	OD ON W. II
Well uneconor 25 sack pl perforation section (1)	mical to produce ug across perfo ns, 100' plug a 850' top & 2300	ce. Proposed pi orations or CI across top and 0' bottom) if a	lugging procedure: BP with 35' cement 100' plug across	t on top	above f salt	
Well uneconor 25 sack pl perforation section (1 is not pul in interva 100' across	mical to produc ug across perfo ns, 100' plug a 850' top & 2300 led below 2500' 1 2300-2500'. s surface casin arker installed	ce. Proposed p orations or CI across top and 0' bottom) if r ', a 25 sack p 100' plug in a ng shoe and 10	lugging procedure: BP with 35' cement	t on top bottom o If 4½" c d inside tion casin	above f salt asing 4½" casir ng stub, asing wit	lg th
Well uneconor 25 sack pl perforatio section (1 is not pul in interva 100' across dry hole ma	mical to produc ug across perfo ns, 100' plug a 850' top & 2300 led below 2500' 1 2300-2500'. s surface casin arker installed	ce. Proposed p orations or CI across top and 0' bottom) if r ', a 25 sack p 100' plug in a ng shoe and 10	lugging procedure: BP with 35' cement 100' plug across not behind pipe. lug will be placed and out of product sacks in top of s	t on top bottom o If 4½" c d inside tion casin	above f salt asing 4½" casir ng stub, asing wit	18 18
Well uneconor 25 sack pl perforatio section (1 is not pul in interva 100' across dry hole ma	mical to produc ug across perfo ns, 100' plug a 850' top & 2300 led below 2500' 1 2300-2500'. s surface casin arker installed	ce. Proposed p orations or CI across top and 0' bottom) if r ', a 25 sack p 100' plug in a ng shoe and 10	lugging procedure: BP with 35' cement 100' plug across not behind pipe. lug will be placed and out of product sacks in top of s	t on top bottom o If 4½" c d inside tion casin	above f salt asing 4½" casir ng stub, asing wit	18 18
Well uneconor 25 sack pl perforatio section (1 is not pul in interva 100' across dry hole ma	mical to produc ug across perfo ns, 100' plug a 850' top & 2300 led below 2500' 1 2300-2500'. s surface casin arker installed	ce. Proposed p orations or CI across top and 0' bottom) if r ', a 25 sack p 100' plug in a ng shoe and 10	lugging procedure: BP with 35' cement 100' plug across not behind pipe. lug will be placed and out of product sacks in top of s	t on top bottom o If 4½" c d inside tion casin	above f salt asing 4½" casir ng stub, asing wit	18 18
Well uneconor 25 sack pl perforatio section (1 is not pul in interva 100' across dry hole ma	mical to produc ug across perfo ns, 100' plug a 850' top & 2300 led below 2500' 1 2300-2500'. s surface casin arker installed	ce. Proposed p orations or CI across top and 0' bottom) if r ', a 25 sack p 100' plug in a ng shoe and 10	lugging procedure: BP with 35' cement 100' plug across not behind pipe. lug will be placed and out of product sacks in top of s	t on top bottom o If 4½" c d inside tion casin	above f salt asing 4½" casir ng stub, asing wit	lg th
Well uneconor 25 sack pl perforatio section (1 is not pul in interva 100' across dry hole ma	mical to produc ug across perfo ns, 100' plug a 850' top & 2300 led below 2500' 1 2300-2500'. s surface casin arker installed	ce. Proposed p orations or CI across top and 0' bottom) if r ', a 25 sack p 100' plug in a ng shoe and 10	lugging procedure: BP with 35' cement 100' plug across not behind pipe. lug will be placed and out of product sacks in top of s	t on top bottom o If 4½" c d inside tion casin	above f salt asing 4½" casir ng stub, asing wit	18 18
Well uneconor 25 sack pl perforatio section (1 is not pul in interva 100' across dry hole ma	mical to produc ug across perfo ns, 100' plug a 850' top & 2300 led below 2500' 1 2300-2500'. s surface casin arker installed	ce. Proposed p orations or CI across top and 0' bottom) if r ', a 25 sack p 100' plug in a ng shoe and 10	lugging procedure: BP with 35' cement 100' plug across not behind pipe. lug will be placed and out of product sacks in top of s	t on top bottom o If 4½" c d inside tion casin	above f salt asing 4½" casir ng stub, asing wit	18 18
Well uneconor 25 sack pl perforatio section (1 is not pul in interva 100' across dry hole ma	mical to produc ug across perfo ns, 100' plug a 850' top & 2300 led below 2500' 1 2300-2500'. s surface casin arker installed	ce. Proposed p orations or CI across top and 0' bottom) if r ', a 25 sack p 100' plug in a ng shoe and 10	lugging procedure: BP with 35' cement 100' plug across not behind pipe. lug will be placed and out of product sacks in top of s	t on top bottom o If 4½" c d inside tion casin	above f salt asing 4½" casir ng stub, asing wit	lg -h
Well uneconor 25 sack pl perforatio section (1 is not pul in interva 100' across dry hole ma	mical to produc ug across perfo ns, 100' plug a 850' top & 2300 led below 2500' 1 2300-2500'. s surface casin arker installed	ce. Proposed p orations or CI across top and 0' bottom) if r ', a 25 sack p 100' plug in a ng shoe and 10	lugging procedure: BP with 35' cement 100' plug across not behind pipe. lug will be placed and out of product sacks in top of s	t on top bottom o If 4½" c d inside tion casin	above f salt asing 4½" casir ng stub, asing wit	18 18
Well uneconor 25 sack pl perforatio section (1 is not pul in interva 100' across dry hole ma	mical to produc ug across perfo ns, 100' plug a 850' top & 2300 led below 2500' 1 2300-2500'. s surface casin arker installed	ce. Proposed p orations or CI across top and 0' bottom) if r ', a 25 sack p 100' plug in a ng shoe and 10	lugging procedure: BP with 35' cement 100' plug across not behind pipe. lug will be placed and out of product sacks in top of s	t on top bottom o If 4½" c d inside tion casin	above f salt asing 4½" casir ng stub, asing wit	18 18
Well uneconor 25 sack pl perforatio section (1 is not pul in interva 100' across dry hole ma	mical to produc ug across perfo ns, 100' plug a 850' top & 2300 led below 2500' 1 2300-2500'. s surface casin arker installed	ce. Proposed p orations or CI across top and 0' bottom) if r ', a 25 sack p 100' plug in a ng shoe and 10	lugging procedure: BP with 35' cement 100' plug across not behind pipe. lug will be placed and out of product sacks in top of s	t on top bottom o If 4½" c d inside tion casin	above f salt asing 4½" casir ng stub, asing wit	18 18
Well uneconor 25 sack pl perforatio section (1 is not pul in interva 100' across dry hole ma	mical to produc ug across perfo ns, 100' plug a 850' top & 2300 led below 2500' 1 2300-2500'. s surface casin arker installed ttom plug.	ce. Proposed p orations or CI across top and 0' bottom) if n ', a 25 sack p 100' plug in a ng shoe and 10 d. Mud between	lugging procedure: BP with 35' cement 100' plug across not behind pipe. lug will be placed and out of product sacks in top of s	t on top bottom o If 4½" c d inside tion casin	above f salt asing 4½" casir ng stub, asing wit	lg -h
Well uneconor 25 sack pl perforation section (1 is not pul in interva 100' across dry hole ma setting box setting box	mical to produce ug across performs, 100' plug a 850' top & 2300 1 2300-2500'. s surface casin arker installed ttom plug.	ce. Proposed pl orations or CI across top and 0' bottom) if r ', a 25 sack pl 100' plug in a ng shoe and 10 d. Mud between	lugging procedure: BP with 35' cement 100' plug across not behind pipe. lug will be placed and out of product sacks in top of s	t on top bottom o If 4½" c i inside ion casin surface ca ir notice	above f salt asing 4½" casir ng stub, asing wit	ng h
Well uneconor 25 sack pl perforation section (1 is not pul in interva 100' across dry hole ma setting box setting box	mical to produce ug across performs, 100' plug a 850' top & 2300 1 2300-2500'. s surface casin arker installed ttom plug.	ce. Proposed pl orations or CI across top and 0' bottom) if r ', a 25 sack pl 100' plug in a ng shoe and 10 d. Mud between	lugging procedure: BP with 35' cement 100' plug across not behind pipe. lug will be placed and out of product sacks in top of s n plugs and 24 hou	t on top bottom o If 4½" c i inside ion casin surface ca ir notice	above f salt asing 4½" casir ng stub, asing wit prior to	ng hh
<ul> <li>Nent to this work.) *</li> <li>Well uneconor</li> <li>25 sack pl</li> <li>perforation</li> <li>section (1.</li> <li>is not pul</li> <li>in interval</li> <li>100' across</li> <li>dry hole may</li> <li>setting box</li> <li>dry hole may</li> <li>setting box</li> </ul>	mical to produce ug across performs, 100' plug a 850' top & 2300 1 2300-2500'. s surface casin arker installed ttom plug.	ce. Proposed plorations or CI across top and 0' bottom) if r ', a 25 sack pl 100' plug in a ng shoe and 10 d. Mud between d. Mud between	lugging procedure: BP with 35' cement 100' plug across not behind pipe. lug will be placed and out of product sacks in top of s n plugs and 24 hou	t on top bottom o If 4½" c i inside tion casin surface c ir notice	above f salt asing 4½" casir ng stub, asing wit prior to	ng hh
<ul> <li>Nent to this work.)</li> <li>Well uneconor</li> <li>25 sack pl</li> <li>perforation</li> <li>section (1,</li> <li>is not pul</li> <li>in interval</li> <li>100' across</li> <li>dry hole may</li> <li>setting box</li> <li>setting box</li> </ul>	mical to produce ug across performs, 100' plug a 850' top & 2300 led below 2500'. Is surface casing arker installed the foregoing is true and the foregoing is true and model of the second er M. Randolph al or State office use)	ce. Proposed plorations or CI across top and 0' bottom) if r ', a 25 sack pl 100' plug in a ng shoe and 10 d. Mud between d. Mud between	lugging procedure: BP with 35' cement 100' plug across not behind pipe. lug will be placed and out of product sacks in top of s n plugs and 24 hou	t on top bottom o If 4½" c i inside tion casin surface c ir notice	above f salt asing 4½" casir ng stub, asing wit prior to	ng hh

.