

HOBBE IM 88241

Form 3160-5
(November 1983)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME Todd Lower S A Unit. Sec.30	
2. NAME OF OPERATOR PLAINS PETROLEUM OPERATING COMPANY		8. FARM OR LEASE NAME	
3. ADDRESS OF OPERATOR 415 W. WALL, SUITE 1000 MIDLAND, TX 79701		9. WELL NO. 13	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit Letter M, 611' FWL & 660' FSL		10. FIELD AND POOL, OR WILDCAT Todd Lower S A Assoc	
14. PERMIT NO.		11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Sec.30, T7S, R36E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4151 GL		12. COUNTY OR PARISH Roosevelt	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

In response to your letter dated Jan. 20, 1994, PPOC plans to plug and abandon this well and requests approval of the following plugging program.

1. Set plug across perfs 4234'-75' (¹⁶10-sx), 140' cmt, Tag plug.

2. Cut and recover approximately 3500' of 5-1/2" casing

* → 3. Set 10-sx plug at TOC - 170' cmt. plug centered on stub. Tag plug.

4. Set 10 sx plug at surface csg shoe @ 285'

5. Set surface plug with marker

API No. 30-041-10497

* additional plug: 170' cmt. plug 2170'-2000'
If the 5 1/2" casing is cut and pulled within
± 300' of this point the stub plug will
suffice for this plug.



18. I hereby certify that the foregoing is true and correct

SIGNED

Bonnie Husband

TITLE

Administrative Assistant

DATE

Jan. 28, 1994

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

approved as modified.

TITLE

DATE

APPROVED
PETER W. CHESTER

FEB 10 1994

*See Instructions on Reverse Side

BUREAU OF LAND MANAGEMENT