

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. NM 0554779
2. NAME OF OPERATOR Humble Oil & Refg		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 1600 - Midland Texas 79701		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit C, 660' FNL, 1980' FWL		8. FARM OR LEASE NAME Andrews Federal
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4444 DF	9. WELL NO. 1
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		10. FIELD AND POOL, OR WILDCAT Chaveroo San Andres
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA S30, T7S, R33E
		12. COUNTY OR PARISH Roosevelt
		13. STATE N.M.=X

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well is uneconomical to produce. Request permission to plug and abandon well as follows:

1. Spot cmt plug from 4364' PBD to 4100'.
2. Cut 4 1/2" CSG @ 3000' and pull.
3. Spot cmt plug from 3050' to 2800' across cut.
4. Spot cmt plug from 2300' to 2200' across top Yates.
5. Spot cmt plug 2000' to 1800' across top Salt.
6. Spot cmt plug 220' to 150' across top surface CSG.
7. Spot cmt plug 30' to 0'.
8. Install dry hole marker & clean location.
9. Mud laden fluid to be placed between plugs.

18. I hereby certify that the foregoing is true and correct

SIGNED

R. L. Berry

TITLE

Unit Head

DATE

6-26-68

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

JUN 28 1968

*See Instructions on Reverse Side

J L GORDON
ACTING DISTRICT ENGINEER