Form	3160-5
(June	1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

N.M. Uil Co	NS. Division Approved Budget Bureau No. 1004-0135
	ILL Expres. March 51, 1993
Hobbs, NM	88240 LC - CC 2-529

6. If Indian, Allottee or Tribe Name

9 A

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
		سر Todd Lower S A Unit Sec 2+
Gas -	Pot	8. Well Name and No.
Name of Operator		<b>₹<del>864</del> <del>25</del>08</b>
Saga Petroleum		9. API Well No.
Address and Telephone No.		30041104785
415 W. Wall, Suite 1900, Midland, TX. 79701		10. Field and Pool, or Exploratory Area
4. Location of Weil (Footage, Sec., T., R., M., or Survey Description) 1980 FNL & 660 FEL Sec 25, T7S R 35E		Todd Lower San Andres
		11. County or Parish, State
		Roosevett
CHECK APPROPRIATE BOX(s	) TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE	OF ACTION
Notice of Intent	Abandonment	Change of Plans
—	Recompletion	New Construction
Subsequent Report	Plugging Back	
		Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
		Dispose Water
directionally drilled, give subsurface locations and meas 1. Set CIBP @ 4200. Dump 26 cement on to 2. 100 ft. plug @ 2035 - 1935. 4. Cut and pull 5 1/2 +/- 1000;.	sured and true vertical depths for all markders and zones p. (perfs 4242 to 4284 ) $35' - ANE$	
Describe Proposed or Completed Operations (Clearly st directionally drilled, give subsurface locations and meas 1. Set CIBP @ 4200. Dump 20 cement on to 2. 100 ft. plug @ 2035 - 1935. 4. Cut and pull 5 1/2 +/- 1000;. 5. Spot 100' plug @ 5 1/2 stub. Tag 6. Spot 100 ft. plug @ 8 5/8 shoe (50 in 50 o 7. Surface plug install dry hoe marker.	tate all pertinet details, and give pertinent dates, includen sured and true vertical depths for all markders and zones p. (perfs 4242 to 4284) $35' - ANE$ 274'	completion or Recompletion Report and Log form.) Ig estimated date of starting any proposed work. If well is pertinent to this work.)*
directionally drilled, give subsurface locations and meas 1. Set CIBP @ 4200. Dump 28 cement on to 2. 100 ft. plug @ 2035 - 1935. 4. Cut and pull 5 1/2 +/- 1000;. 5. Spot 100' plug @ 5 1/2 stub. Tag 6. Spot 100 ft. plug @ 8 5/8 shoe (50 in 50 o	tate all pertinet details, and give pertinent dates, includen sured and true vertical depths for all markders and zones p. (perfs 4242 to 4284) $35' - ANE$ 274'	completion or Recompletion Report and Log form.) Ig estimated date of starting any proposed work. If well is pertinent to this work.)*
directionally drilled, give subsurface locations and meas 1. Set CIBP @ 4200. Dump 28 cement on to 2. 100 ft. plug @ 2035 - 1935. 4. Cut and pull 5 1/2 +/- 1000;. 5. Spot 100' plug @ 5 1/2 stub. Tag 6. Spot 100 ft. plug @ 8 5/8 shoe (50 in 50 o	tate all pertinet details, and give pertinent dates, includen sured and true vertical depths for all markders and zones p. (perfs 4242 to 4284)	Completion or Recompletion Report and Log form.) Ig estimated date of starting any proposed work. If well is pertinent to this work.)* STAC
directionally drilled, give subsurface locations and meas 1. Set CIBP @ 4200. Dump 20 cement on to 2. 100 ft. plug @ 2035 - 1935. 4. Cut and pull 5 1/2 +/- 1000;. 5. Spot 100' plug @ 5 1/2 stub. Tag 6 Spot 100 ft. plug @ 8 5/8 shoe (50 in 50 o 7 Surface plug install dry hoe marker.	tate all pertinet details, and give pertinent dates, includen sured and true vertical depths for all markders and zones p. (perfs 4242 to 4284) $35' - ANE$ 274'	completion or Recompletion Report and Log form.) Ig estimated date of starting any proposed work. If well is pertinent to this work.)*
directionality drilled, give subsurface locations and meas 1. Set CIBP @ 4200. Dump 20 cement on to 2. 100 ft. plug @ 2035 - 1935. 4. Cut and pull 5 1/2 +/- 1000;. 5. Spot 100' plug @ 5 1/2 stub. Tag 5. Spot 100 ft. plug @ 8 5/8 shoe (50 in 50 o 7. Surface plug install dry hoe marker. 8. Surface plug install dry hoe marker.	tate all pertinet details, and give pertinent dates, includen sured and true vertical depths for all markders and zones p. (perfs 4242 to 4284)	Completion or Recompletion Report and Log form.) Ig estimated date of starting any proposed work. If well is pertinent to this work.)* STAC
directionality drilled, give subsurface locations and meas 1. Set CIBP @ 4200. Dump 20 cement on to 2. 100 ft. plug @ 2035 - 1935. 4. Cut and pull 5 1/2 +/- 1000;. 5. Spot 100' plug @ 5 1/2 stub. Tag 5. Spot 100 ft. plug @ 8 5/8 shoe (50 in 50 o 7. Surface plug install dry hoe marker. 5. Surface plug install dry hoe marker. 6. I hereby certify that the foregoing is true and correct igned	tate all pertinet details, and give pertinent dates, includen sured and true vertical depths for all markders and zones p. (perfs 4242 to 4284)	Completion or Recompletion Report and Log form.) Ig estimated date of starting any proposed work. If well is pertinent to this work.)* STAC
directionality drilled, give subsurface locations and mease 1. Set CIBP @ 4200. Dump 20 cement on to 2. 100 ft. plug @ 2035 - 1935. 4. Cut and pull 5 1/2 +/- 1000;. 5. Spot 100' plug @ 5 1/2 stub. Tag 6. Spot 100 ft. plug @ 8 5/8 shoe (50 in 50 o 7. Surface plug install dry hoe marker. 8. Surface plug install dry hoe marker. 4. I hereby certify that the foregoing is true and correct igned	tate all pertinet details, and give pertinent dates, includen sured and true vertical depths for all markders and zones p. (perfs 4242 to 4284 ) 35 ~ AND 274 ut) Bottom of shoe @ 334'. Tag	Completion or Recompletion Report and Log form.) g estimated date of starting any proposed work. If well is pertinent to this work.)* STAC Date 08/16/00