

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

HOBBBS, NM 88241
SUBMIT IN TRIPL
(Other instructions on re-

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-0139989A
2. NAME OF OPERATOR PLAINS PETROLEUM OPERATING COMPANY		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 415 W. WALL, SUITE 1000 MIDLAND, TX 79701		7. UNIT AGREEMENT NAME Todd Lower S A Unit. Sec.30
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit Letter L, 611' FWL & 1980' FSL		8. FARM OR LEASE NAME
14. PERMIT NO. 30-041-10629	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4148 GL	9. WELL NO. 12
		10. FIELD AND POOL, OR WILDCAT Todd Lower S A Assoc
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec.30, T7S, R36E
		12. COUNTY OR PARISH Roosevelt
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☒
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

In response to your letter dated Jan. 20, 1994, PPOC plans to plug and abandon this well and requests approval of the following plugging program.

1. Set plug on top of the CIBP set at 4206' above perfs 4232'-66' (10 sx)
2. Cut and recover approximately 3500' of 5-1/2" casing
3. Set ~~10 sx~~ plug at TOC 170' cmt. plug centered on 5 1/2" casing steel. Tag plug
4. Set ~~10 sx~~ plug at surface csg shoe @ 281' 26 sx, 331'-231'. Tag plug.
5. Set surface plug with marker
minimum 50' cmt. plug.

API No. 30-041-10629

* additional plug: 170' cmt., 2420'-2000'
If the 5 1/2" casing is cut & pulled within
± 300' of this point the stub-plug will
suffice for this plug

18. I hereby certify that the foregoing is true and correct

SIGNED

Bonnie Husband

TITLE

Administrative Assistant

DATE

Jan. 28, 1994

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY: *approved as modified.*

DATE

FEB 10 1994

*See Instructions on Reverse Side