## ENERGY AND MINERALS DEPARTMENT

	T	
DISTRIBUTION		
SANTA FE		
FILE		
U.1.0.1.		
LAND OFFICE		
CREATOR	T	

a c s	and pull ± 2000' of casing shoe 475' to surface and erect dr	375'. Tag pry hole marke	Olug and load her.  SOA MUST BE NOTED TO THE MORE AND THE MORE FOR THE MORE FOR THE MORE THE	THEED 24 THEE OF	45 sxs ceme Spot 10 s	xs cement pl	ss surface	
a c s	casing shoe 475' to surface and erect dr	375'. Tag pry hole marke	LOCA MUST BE NOTED TO THE STORE THE	THEED 24 THEE OF	45 sxs ceme Spot 10 s		ss surface	
a	casing shoe 475' to	375'. Tag p	lug and load h		45 sxs ceme		ss surface	Ī
	Describe Proposed or Complete wprk) SEE RULE 1103.  10-15-87" Set CIBP	@ 4150'. Sp	oot 3 sxs cemen	t on top of p				sed
	OTHER	0		OTHER	int dates includi-	estimated date of	Martins any propa	
75.	MPORARILY ABANDON		PLUG AND ABANDON X	REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE	<del></del>		ING CASING  ND ABANDONMENT	
16.		k Appropriate l	Box To Indicate N O:	ature of Notice,	•	her Data TREPORT OF:		
		15. E	levation (Show whether 4325 KDB			12. County Roosevelt		
			TOWNSHIP 7S					
	Occition of Well  WHIT LETTER M				O PEET PROM	10. Field and Poo	£ 1	
3. A	American Trading and Address of Operator			70701		9. Well No.	State "20"	
	dame of Operator	Production	Cornoration			8. Farm or Lease		
ī.		PROPOSALS TO DRILL CATION FOR PERMIT	" (FORM C-101) FOR SUC	H PROPOSALS.)	ESERVOIA,	7, Unit Agreement	Name	77.
	SUN	DRY NOTICES /	AND REPORTS ON	WELLS		0G-930		17
	DERATOR					State X  5. State Oil & Gas	Fen L	<u>]</u>
					•	5a. Indicate Type	of Lease	
	FILE U.S.G.S.		SANTA FE, NEW	MEXICO 8750	)1		Revised 10-1	