

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Summary of Instructions on Reverse Side

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME Todd Lower S A Unit, Sec.30
2. NAME OF OPERATOR PLAINS PETROLEUM OPERATING COMPANY	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR 415 W. WALL, SUITE 1000 MIDLAND, TX 79701	9. WELL NO. 6
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit Letter F, 1873' FWL & 1980' FNL	10. FIELD AND POOL, OR WILDCAT Todd Lower S A Assoc
14. PERMIT NO. 30-041-20012	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec.30, T7S, R36E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4151 GL	12. COUNTY OR PARISH Roosevelt
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PCLL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

In response to your letter dated Jan. 20, 1994, PPOC plans to plug and abandon this well and requests approval of the following plugging program.

1. Set plug across perfs 4230'-64' (10' sx) *220'-440' tag plug.*
2. Cut and recover approximately 3650' of 5-1/2" casing *130' cut plug across steel, tag plug.*
3. Set 10' sx plug at TOC
- * 4. Set ~~10'~~ plug at surface csg shoe @ 294', *26' sx, 344'-344' tag plug.*
5. Set surface plug with marker *minimum 50' cut plug.*

API No. 30-041-20012

* additional plug; 170' cut, 2120'-2000'.
If the 5 1/2" casing is cut and pulled within
± 300' of this point the steel plug will
suffice for this plug.



18. I hereby certify that the foregoing is true and correct

SIGNED

Bonnie Husband

TITLE

Administrative Assistant

DATE

Jan. 28, 1994

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY: *Approved as modified.*

DATE

FEB 10 1994

*See Instructions on Reverse Side