| NO. OF COPIES NECEIVED | | Form C-103 |
|---|--|---|
| DISTRIBUTION | | Supersedes Old |
| SANTA FE | NEW MEXICO OIL CONSERVATION COMMINSTON OF THE | C-102 and C-103 D. Ettective 1-1-65 |
| FILE | | 77 7: 6: |
| U.S.G.S. | Ju 5 9 20 | Salfrelegate Type of Lease |
| LAND OFFICE | 302 3 3 19 | MStall Fee XXX |
| OPERATOR | | 5, State Oil & Gas Lease No. |
| | | |
| | RY NOTICES AND REPORTS ON WELLS OPOSALS TO ORILL OR TO DEEPEN OR PLUE BACK TO A DIFFERENT RESERVOIR. TION FOR PERMIT—" (FORM C-101) FOR SUCH PROPOSALS.) | |
| OIL GAS WELL WELL | other. Drilling Well | 7. Unit Agreement Name |
| 2. Name of Operator | | 8. Farm or Lease Name |
| Southern Minerals Co | prporation | S. E. Cone |
| 3. Address of Operator | | 9. Well No. |
| P. 0. Box 716 Co | orpus Christi, Texas (8403 | #1 10. Field and Pool, or Wildcat |
| L 3 | 1980 FEET FROM THE South LINE AND 660 FEET FROM | |
| UNIT LETTER | FEET FROM THE LINE AND FEET FROM | Undesignated |
| West | 15 TOWNSHIP 8-S RANGE 34-E NMPM. | |
| THE LINE, SECT | TOWNSHIP RANGE NMPM. | |
| | 15. Elevation (Show whether DF, RT, GR, etc.) | 12. County |
| | 4277.6 Gr. | |
| <i>"</i> | | Roosevelt |
| | Appropriate Box To Indicate Nature of Notice, Report or Oth | er Data |
| NOTICE OF I | NTENTION TO: SUBSEQUENT | REPORT OF: |
| | | |
| PERFORM REMEDIAL WORK | PLUS AND ABANDON REMEDIAL WORK | ALTERING CASING |
| TEMPORARILY ABANDON | COMMENCE DRILLING OPHS. | PLUG AND ABANDONMENT |
| | | |
| PULL OR ALTER CASING | CHANGE PLANS CASING TEST AND CEMENT JOB | ,,, |
| PULL OR ALTER CABING | CHANGE PLANS CASING TEST AND CEMENT JQB | , ` |
| OTHER | | |
| OTHER | OTHER | |
| OTHER | | estimated date of starting any proposed |
| 17, Describe Proposed or Completed O work) SEE RULE 10 / | OTHER | estimated date of starting any proposed |
| OTHER 17. Describe Proposed or Completed O | Perations (Clearly state all pertinent details, and give pertinent dates, including o | |
| 17. Describe Proposed or Completed O work) SEE RULE 19 | Pulled tubing. Spotted 15 sacks cement from | |
| 17, Describe Proposed or Completed O work) SEE RULE 10 / | Perations (Clearly state all pertinent details, and give pertinent dates, including o | |
| 17. Describe Proposed or Completed O work) SEE RULE 10 May 25, 1967 May 26, 1967 | Pulled tubing. Spotted 15 sacks cement from Shot 42" casing off at 3000. | 43 75 *-4 576 *. |
| 17. Describe Proposed or Completed O work) SEE RULE 19 | Pulled tubing. Spotted 15 sacks cement from Shot 41 casing off at 3000. Spotted cement plugs at depths as indicated in the sacks cement from the sacks cement plugs at depths as indicated in the sacks cement plugs at depths as a sacks cement plugs at depths and depths are a sacks cement plugg | 43 75 *-4 576 *. |
| 17. Describe Proposed or Completed O work) SEE RULE 10 May 25, 1967 May 26, 1967 | Pulled tubing. Spotted 15 sacks cement from Shot 41 casing off at 3000. Spotted cement plugs at depths as indicated 25 sacks from 2518 to 2998. | 43 75 *-4 576 *. |
| 17. Describe Proposed or Completed O work) SEE RULE 10 May 25, 1967 May 26, 1967 | Pulled tubing. Spotted 15 sacks cement from Shot 41" casing off at 3000. Spotted cement plugs at depths as indicated 25 sacks from 2518 to 2998. 25 sacks from 2516 to 2596. | 43 75 *-4 576 *. |
| 17. Describe Proposed or Completed O work) SEE RULE 10 May 25, 1967 May 26, 1967 | Pulled tubing. Spotted 15 sacks cement from Shot 41 casing off at 3000. Spotted cement plugs at depths as indicated 25 sacks from 2518 to 2998. 25 sacks from 2516 to 2596. 25 sacks from 2074 to 2154. | 43 75 *-4 576 *. |
| 17. Describe Proposed or Completed O work) SEE RULE 10 May 25, 1967 May 26, 1967 | Pulled tubing. Spotted 15 sacks cement from Shot 42" casing off at 3000'. Spotted cement plugs at depths as indicated 125 sacks from 2518' to 2998' 25 sacks from 2516' to 2596' 25 sacks from 2074' to 2154' 25 sacks from 326' to 408' | 43 75 *-4 576 *. |
| 17. Describe Proposed or Completed O work) SEE RULE 10 May 25, 1967 May 26, 1967 | Pulled tubing. Spotted 15 sacks cement from Shot 4½" casing off at 3000'. Spotted cement plugs at depths as indicated 125 sacks from 2518' to 2998' 25 sacks from 2516' to 2596' 25 sacks from 2074' to 2154' 25 sacks from 326' to 408' 10 sacks in top of casing | 43 75 *-4 576 *. |
| 17. Describe Proposed or Completed O work) SEE RULE 10 May 25, 1967 May 26, 1967 | Pulled tubing. Spotted 15 sacks cement from Shot 41 casing off at 3000. Spotted cement plugs at depths as indicated 25 sacks from 2518 to 2998. 25 sacks from 2516 to 2596. 25 sacks from 2074 to 2154. 25 sacks in top of casing Placed marker on well | 4375*-4576*. below: |
| 17. Describe Proposed or Completed O work) SEE RULE 10 May 25, 1967 May 26, 1967 | Pulled tubing. Spotted 15 sacks cement from Shot 4½" casing off at 3000'. Spotted cement plugs at depths as indicated 125 sacks from 2518' to 2998' 25 sacks from 2516' to 2596' 25 sacks from 2074' to 2154' 25 sacks from 326' to 408' 10 sacks in top of casing | 4375*-4576*. below: |
| May 25, 1967 May 27, 1967 | Pulled tubing. Spotted 15 sacks cement from Shot 41 casing off at 3000. Spotted cement plugs at depths as indicated 25 sacks from 2518 to 2998. 25 sacks from 2516 to 2596. 25 sacks from 2074 to 2154. 25 sacks in top of casing Placed marker on well | 4375*-4576*. below: |
| May 25, 1967 May 27, 1967 | Pulled tubing. Spotted 15 sacks cement from Shot 42" casing off at 3000'. Spotted cement plugs at depths as indicated to 25 sacks from 2518' to 2998' 25 sacks from 2516' to 2596' 25 sacks from 2074' to 2154' 25 sacks from 326' to 408' 10 sacks in top of casing Placed marker on well Pits have been filled & location levelled, & | 4375*-4576*. below: |
| May 25, 1967 May 27, 1967 | Pulled tubing. Spotted 15 sacks cement from Shot 41 casing off at 3000. Spotted cement plugs at depths as indicated 25 sacks from 2518 to 2998. 25 sacks from 2516 to 2596. 25 sacks from 2074 to 2154. 25 sacks in top of casing Placed marker on well | 4375*-4576*. below: |
| May 25, 1967 May 26, 1967 May 27, 1967 | Pulled tubing. Spotted 15 sacks cement from Shot 42" casing off at 3000'. Spotted cement plugs at depths as indicated to 25 sacks from 2518' to 2998' 25 sacks from 2516' to 2596' 25 sacks from 2074' to 2154' 25 sacks from 326' to 408' 10 sacks in top of casing Placed marker on well Pits have been filled & location levelled, & | 4375*-4576*. below: |
| May 25, 1967 May 26, 1967 May 27, 1967 | Pulled tubing. Spotted 15 sacks cement from Shot 42" casing off at 3000'. Spotted cement plugs at depths as indicated to 25 sacks from 2518' to 2998' 25 sacks from 2516' to 2596' 25 sacks from 2074' to 2154' 25 sacks from 326' to 408' 10 sacks in top of casing Placed marker on well Pits have been filled & location levelled, & | 4375*-4576*. below: |
| May 25, 1967 May 26, 1967 May 27, 1967 | Pulled tubing. Spotted 15 sacks cement from Shot 42" casing off at 3000'. Spotted cement plugs at depths as indicated to 25 sacks from 2518' to 2998' 25 sacks from 2516' to 2596' 25 sacks from 2074' to 2154' 25 sacks from 326' to 408' 10 sacks in top of casing Placed marker on well Pits have been filled & location levelled, & | 4375*-4576*. below: |
| May 25, 1967 May 26, 1967 May 27, 1967 | Pulled tubing. Spotted 15 sacks cement from Shot 41" casing off at 3000'. Spotted cement plugs at depths as indicated 125 sacks from 2518' to 2998'. 25 sacks from 2516' to 2596'. 25 sacks from 326' to 408'. 10 sacks in top of casing Placed marker on well Pits have been filled & location levelled, & | 4375*-4576*. below: |
| May 25, 1967 May 26, 1967 May 27, 1967 | Pulled tubing. Spotted 15 sacks cement from Shot 42" casing off at 3000'. Spotted cement plugs at depths as indicated to 25 sacks from 2518' to 2998' 25 sacks from 2516' to 2596' 25 sacks from 2074' to 2154' 25 sacks from 326' to 408' 10 sacks in top of casing Placed marker on well Pits have been filled & location levelled, & | 4375*-4576*. below: |
| May 25, 1967 May 26, 1967 May 27, 1967 | Pulled tubing. Spotted 15 sacks cement from Shot 41" casing off at 3000'. Spotted cement plugs at depths as indicated 125 sacks from 2518' to 2998' 25 sacks from 2510' to 2596' 25 sacks from 2074' to 2154' 25 sacks from 326' to 408' 10 sacks in top of casing Placed marker on well Pits have been filled & location levelled, & | 4375 *- 4576 *. below: cleared of junk. |
| May 25, 1967 May 26, 1967 May 27, 1967 | Pulled tubing. Spotted 15 sacks cement from Shot 41" casing off at 3000'. Spotted cement plugs at depths as indicated 125 sacks from 2518' to 2998'. 25 sacks from 2518' to 2998'. 25 sacks from 2516' to 2596'. 25 sacks from 326' to 408'. 10 sacks in top of casing Placed marker on well. Pits have been filled & location levelled, & WELL NOW READY FOR INSPECTION. | 4375*-4576*. below: |
| 17. Describe Proposed or Completed Omork) SEE RULE 17 May 25, 1967 May 27, 1967 May 27, 1967 | Pulled tubing. Spotted 15 sacks cement from Shot 41" casing off at 3000'. Spotted cement plugs at depths as indicated 125 sacks from 2518' to 2998' 25 sacks from 2510' to 2596' 25 sacks from 2074' to 2154' 25 sacks from 326' to 408' 10 sacks in top of casing Placed marker on well Pits have been filled & location levelled, & | 4375 *- 4576 *. below: cleared of junk. |

CONDITIONS OF APPROVAL, IF ANY: