

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBBS OFFICE O. C. C.  
NEW MEXICO OIL CONSERVATION COMMISSION

JUN 29 2 24 PM '67

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name E.D. Morris
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat
12. County Roosevelt

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Cactus Drilling Corp. of Texas 3. Address of Operator P.O. Box 2068, Hobbs, New Mexico 4. Location of Well UNIT LETTER <u>E</u> <u>1980</u> FEET FROM THE <u>N</u> LINE AND <u>660</u> FEET FROM THE <u>W</u> LINE, SECTION <u>3</u> TOWNSHIP <u>7s</u> RANGE <u>35e</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4229 GL
---

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOH <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled 7 7/8" hole to 4350' and ran open hole logs. obtained permission from Eric Engbrecht to P&A.  
Set plugs at the following depths:  
25 sx at 4300'  
25 sx at 3400'  
25 sx at 2500'  
25 sx at ~~2500~~ 900'  
25 sx at 350' in and out of surface casing  
10 sx at surface  
Dry hole marker set in 8 5/8 casing location clean and abandon.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Geo. W. Baker</u>	TITLE <u>Vice-President</u>	DATE <u>6-29-67</u>
APPROVED BY <u>John W. Ryan</u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		