NO. OF COPIES RECEIVED		-			Form C-103	
DISTRIBUTION					Supersedes Old C-102 and C-10	
ANTA FE	NEW M	EXICO OIL CONSI	ERVATION COMMISSION		Effective 1-1-6	
.s.g.s.				50	State X	Fee
AND OFFICE				-	State Oil & Gas	
PERATOR					SG & FC #	
CI NDD		D REPORTS ON	WELLS			<u>IIIIIIII</u>
	POSALS TO DAILL OR ION FOR PERMIT -"	TO DEEPEN OR PLUG B.	ACK TO A DIFFERENT RESERVOIR		Unit Agreement	Name
	OTHER.				_	
Name of Operator				8.	Form or Lease	Name
Monument Energy Corpo	ration		·	·	HSG	
3. Address of Operator Box 1476, Lovington, New Mexico 88260					9. Well No. 4	
Box 1476, Lovington, Location of Well	New Mexico d	80200		1	0. Field and Poo	l, or Wildcat
	660	south	LINE AND 1980	FEET FROM	Chaveroo S	an Andres
UNIT LETTER	FEET PR	OM THE	LINE AND	R		
east	26	75	RANGE 32E	NMPM. (		
THE LINE, SECTION					////////	HHHHH
		vation (Show whether	DF, RT, GR, etc.)		2, County	
		471.1 KB			oosevelt	
	Appropriate Bo NTENTION TO:		ature of Notice, Repo	EQUENT F	REPORT OF:	
				 		NG CASING
PERFORM REMEDIAL WORK	PL	UG AND ABANDON	REMEDIAL WORK			ND ABANDONMENT
TEMPORARILY ABANDON	•		COMMENCE DRILLING OPNS. Casing test and cement JQI			
PULL OR ALTER CASING	CH.	ANGE PLANS	OTHER		•	
					• •	
OTHER	i				etimated date of	tarting any prop
7. Describe Proposed or Completed O	perations (Clearly s	state all pertinent det	ails, and give pertinent dates		timated date of s	starting any propo
	perations (Clearly s	state all pertinent det	ails, and give pertinent dates		timated date of s	starting any propo
Pulled rods and tubin casing @ 1203 and red @ casing stubb. Pull casing. Set P & A ma	ng. Set CIB covered same led tubing t arker with 1	p @ 4000' and . Went in ho o 350' and se O sacks cemen	circulated hole w le with tubing and t 35 sack plug @ b t @ surface.	, including es vith 10# 1 set 35	mud. Shot sack plug	
<ul> <li>Proposed or Completed O work) SEE RULE 1703.</li> <li>Pulled rods and tubin casing @ 1203 and rec @ casing stubb. Pull</li> </ul>	ng. Set CIB covered same led tubing t arker with 1	p @ 4000' and . Went in ho o 350' and se O sacks cemen	circulated hole w le with tubing and t 35 sack plug @ b t @ surface.	, including es vith 10# 1 set 35	mud. Shot sack plug	
<ul> <li>Pulled rods and tubin casing @ 1203 and red @ casing stubb.</li> <li>Pulled rods And red pulled rods.</li> </ul>	ng. Set CIB covered same led tubing t arker with 1	p @ 4000' and . Went in ho o 350' and se O sacks cemen	circulated hole w le with tubing and t 35 sack plug @ b t @ surface.	, including es vith 10# 1 set 35	mud. Shot sack plug	
7. Describe Proposed or Completed O work) SEE RULE 1703. Pulled rods and tubin casing @ 1203 and red @ casing stubb. Pull casing. Set P & A ma	ng. Set CIB covered same led tubing t arker with 1	p @ 4000' and . Went in ho o 350' and se O sacks cemen	circulated hole w le with tubing and t 35 sack plug @ b t @ surface.	, including es vith 10# 1 set 35	mud. Shot sack plug	
Pulled rods and tubin casing @ 1203 and red @ casing stubb. Pull casing. Set P & A ma	ng. Set CIB covered same led tubing t arker with 1	p @ 4000' and . Went in ho o 350' and se O sacks cemen	circulated hole w le with tubing and t 35 sack plug @ b t @ surface.	, including es vith 10# 1 set 35	mud. Shot sack plug	
7. Describe Proposed or Completed O work) SEE RULE 1703. Pulled rods and tubin casing @ 1203 and red @ casing stubb. Pull casing. Set P & A ma	ng. Set CIB covered same led tubing t arker with 1	p @ 4000' and . Went in ho o 350' and se O sacks cemen	circulated hole w le with tubing and t 35 sack plug @ b t @ surface.	, including es vith 10# 1 set 35	mud. Shot sack plug	
7. Describe Proposed or Completed O work) SEE RULE 1703. Pulled rods and tubin casing @ 1203 and red @ casing stubb. Pull casing. Set P & A ma	ng. Set CIB covered same led tubing t arker with 1	p @ 4000' and . Went in ho o 350' and se O sacks cemen	circulated hole w le with tubing and t 35 sack plug @ b t @ surface.	, including es vith 10# 1 set 35	mud. Shot sack plug	
7. Describe Proposed or Completed O work) SEE RULE 1703. Pulled rods and tubin casing @ 1203 and red @ casing stubb. Pull casing. Set P & A ma	ng. Set CIB covered same led tubing t arker with 1	p @ 4000' and . Went in ho o 350' and se O sacks cemen	circulated hole w le with tubing and t 35 sack plug @ b t @ surface.	, including es vith 10# 1 set 35	mud. Shot sack plug	
7. Describe Proposed or Completed O work) SEE RULE 1703. Pulled rods and tubin casing @ 1203 and red @ casing stubb. Pull casing. Set P & A ma	ng. Set CIB covered same led tubing t arker with 1	p @ 4000' and . Went in ho o 350' and se O sacks cemen	circulated hole w le with tubing and t 35 sack plug @ b t @ surface.	, including es vith 10# 1 set 35	mud. Shot sack plug	
<ul> <li>Pulled rods and tubin casing @ 1203 and red @ casing stubb.</li> <li>Pulled rods And red pulled rods.</li> </ul>	ng. Set CIB covered same led tubing t arker with 1	p @ 4000' and . Went in ho o 350' and se O sacks cemen	circulated hole w le with tubing and t 35 sack plug @ b t @ surface.	, including es vith 10# 1 set 35	mud. Shot sack plug	
7. Describe Proposed or Completed O work) SEE RULE 1703. Pulled rods and tubin casing @ 1203 and red @ casing stubb. Pull casing. Set P & A ma	ng. Set CIB covered same led tubing t arker with 1	p @ 4000' and . Went in ho o 350' and se O sacks cemen	circulated hole w le with tubing and t 35 sack plug @ b t @ surface.	, including es vith 10# 1 set 35	mud. Shot sack plug	
7. Describe Proposed or Completed O work) SEE RULE 1703. Pulled rods and tubin casing @ 1203 and rec @ casing stubb. Pull casing. Set P & A ma Used Permian Basin Ca	ng. Set CIB covered same led tubing t arker with 1 asing Puller	p @ 4000' and . Went in ho o 350' and se O sacks cemen s to plug wel	circulated hole w le with tubing and t 35 sack plug @ b t @ surface. 1.	, including es vith 10# 1 set 35	mud. Shot sack plug	
<ul> <li>Pulled rods and tubin casing @ 1203 and red @ casing stubb. Pull casing. Set P &amp; A ma</li> <li>Used Permian Basin Ca</li> </ul>	ng. Set CIB covered same led tubing t arker with 1 asing Puller	p @ 4000' and . Went in ho o 350' and se O sacks cemen s to plug wel	circulated hole w le with tubing and t 35 sack plug @ b t @ surface. 1.	, including es vith 10# 1 set 35	mud. Shot sack plug	
17. Describe Proposed or Completed O work) SEE RULE 1703. Pulled rods and tubin casing @ 1203 and red @ casing stubb. Pull casing. Set P & A ma	ng. Set CIB covered same led tubing t arker with 1 asing Puller	p @ 4000' and . Went in ho o 350' and se O sacks cemen s to plug wel	circulated hole w le with tubing and t 35 sack plug @ b t @ surface. 1.	, including es	mud. Shot sack plug surface	
<ul> <li>17. Describe Proposed or Completed Owork) SEE RULE 1703.</li> <li>Pulled rods and tubin casing @ 1203 and red @ casing stubb. Pull casing. Set P &amp; A material Set P &amp; A &amp;</li></ul>	ng. Set CIB covered same led tubing t arker with 1 asing Puller	p @ 4000' and . Went in ho o 350' and se O sacks cemen s to plug wel	circulated hole w le with tubing and t 35 sack plug @ b t @ surface. 1. 1.	, including es	mud. Shot sack plug surface	-
<ul> <li>17. Describe Proposed or Completed Owork) SEE RULE 1703.</li> <li>Pulled rods and tubin casing @ 1203 and red @ casing stubb. Pull casing. Set P &amp; A material Set P &amp; A &amp;</li></ul>	ng. Set CIB covered same led tubing t arker with 1 asing Puller	p @ 4000' and . Went in ho o 350' and se O sacks cemen s to plug wel	circulated hole w le with tubing and t 35 sack plug @ b t @ surface. 1. 1.	, including es	mud. Shot sack plug surface	-

