

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Plug</b>	7. Unit Agreement Name
2. Name of Operator <b>FLR Oil Company</b>	8. Farm or Lease Name <b>State 30</b>
3. Address of Operator <b>Box 953 Midland Texas 79701</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>N</b> , <b>660</b> FEET FROM THE <b>south</b> LINE AND <b>1980</b> FEET FROM THE <b>west</b> LINE, SECTION <b>30</b> TOWNSHIP <b>7</b> RANGE <b>33</b> NMPM.	10. Field and Pool, or Wildcat <b>Chaveroo (San Andres)</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4442 GR</b>	12. County <b>Roosevelt</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well drilled to TD of 4450'. Well plugged 2-17-72 as follows:

Set 25 sx plug over the perfs from 4186'-4396'. Shot off 4 1/2" @ 3510'. Set 25 sx plug on stub. Set 25 sx plug in and out of surface @ 1819. 10 sx @ surface. Will notify when ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED <u>Lillian Jones</u>	TITLE <u>Agent</u>	DATE <u>March 27, 1972</u>	
APPROVED BY <u>John W. Runyan</u>		TITLE <u>Geologist</u>	DATE <u>10-1-77</u>
CONDITIONS OF APPROVAL, IF ANY:			