| Form 3160-5 (November 1983) | U. FED'STATES | SUBMIT IN TRIP. ATE. (Other instructions on re- | rorm approved. Budget Bureau No Expires August 3 | - 1004-0135 L. 1985 | | | | | |
|--|---|---|---|------------------------|----------------|---------------------------------|--------------------------------|----------------------|-----------|
| (Formerly 9-331) DEPA | RTMENT OF THE INTER | IOR verse side) | 5. LEASE DESIGNATION AN | | | | | | |
| BUREAU OF LAND MANAGEMENT | | | NM0509201 | | | | | | |
| (Do not use this form for | NOTICES AND REPORTS proposals to drill or to deepen or plus PLICATION FOR PERMIT—" for such i | back to a different reservoir. | 6. IF INDIAN, ALLOTTEE O | R TRIBE NAME | | | | | |
| 1. | | | 7. UNIT AGREEMENT NAME | | | | | | |
| OIL GAS WELL OTHER 2. NAME OF OPERATOR | | | Bhuitt San Andres Unit Sec. 18 8. FARM OR LEASE NAME | | | | | | |
| | | | | | | LEUM OPERATING COMPAN | Y | 9. WELL NO. | |
| 3. ADDRESS OF OPERATOR 415 W. WALL, SUITE 1000 MIDLAND, TX 79701 | | | 12 | | | | | | |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit Letter L, 660' FWL & 1980' FSL | | | 10. FIELD AND POOL, OR WILDCAT Bluitt San Andres Assoc. 11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA Sec. 18, T8S, R38E | | | | | | |
| | | | | | 14. PERMIT NO. | 15. ELEVATIONS (Show whether D | | 12. COUNTY OR PARISH | .3. STATE |
| | | | | | | 3985 | 5 GL | Roosevelt | NM |
| | | | | | 16. Chec | k Appropriate Box To Indicate 1 | Nature of Notice, Report, or O | ther Data | |
| | | | | | | INTENTION TO: | , | EN'T REPORT OF: | |
| | | | 1 | | | | | | |
| TEST WATER SHUT-OFF | PCLL OR ALTER CASING | WATER SHUT-OFF | BEPAIRING WEI | | | | | | |
| SHOOT OR ACIDIZE | MULTIPLE COMPLETE | PRACTURE TREATMENT SHOOTING OR ACIDIZING | ALTERING CASI ABANDONMENT | · | | | | | |
| REPAIR WELL | CHANGE PLANS | (Other) | ABANDUN MENT | | | | | | |
| (Other) | | (Nors: Report results | of multiple completion on tion Report and Log form. | Weii | | | | | |
| 2. Cut and recover approx 3. Set 10 sx plug across s 4. Set 10 sx plug across s 5. Set surface plug with r | 18 1676'-4713' (10 sx) . 140 cmd ximately 3000' of 5-1/2" casing FOC 130' cmt. play c surface csg shoe @ 295'; 16 to marker manumen 50: | entered on 52 "steel". x cout, plug, 345 - "cout plug. | Tag plug. 245! Tag pla | 9- | | | | | |
| (This space for Federal or State | TITLE | Administrative Assistant | | 994 | | | | | |
| approved | as mortified - | | I.e. | | | | | | |

- Australiani

*See Instructions on Reverse Side