

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.
NM044216

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Bluitt San Andres Unit Sec.13

8. FARM OR LEASE NAME

9. WELL NO.

10

10. FIELD AND POOL, OR WILDCAT

Bluitt San Andres Assoc.

11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA

Sec.13, T8S, R37E

12. COUNTY OR PARISH 13. STATE

Roosevelt

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

PLAINS PETROLEUM OPERATING COMPANY

3. ADDRESS OF OPERATOR

415 W. WALL, SUITE 1000 MIDLAND, TX 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit Letter J, 1980' FSL & 1980' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3997 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PCLL OR ALTER CASING

☐
☐
☒
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

In response to your letter dated Jan. 20, 1994, PPOC plans to plug and abandon this well and requests approval of the following plugging program.

1. Set plug across perfs 4645'-77' ¹⁸ (10 sx) . 140' cmt. plug 4687' - 4547'. Tag plug.
2. Cut and recover approximately 3000' of 5-1/2" casing
3. * → Set 10 sx plug at TOC 130' cmt. plug centered on 4 1/2" stub, tag plug.
4. Set 10 sx plug at surface csg shoe @ 286'. 26sx, 100' cmt. plug, centered on shoe (326' - 236'), tag plug.
5. Set surface plug with marker. Minimum 50' cmt. surface plug.

API No. 30-041-20168

* additional plug: 170' cmt. 2200' - 2090'

18. I hereby certify that the foregoing is true and correct

SIGNED

Bonnie Hubbard

TITLE

Administrative Assistant

DATE

Jan. 28, 1994

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

approved as modified

TITLE

DATE

FEB 1 1994