

Form 3160-5
(November 1983)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N. M. OIL CONVS. COMMISSION
P.O. BOX 1980
HOBBS, NM 88241

88241
SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM044216
2. NAME OF OPERATOR PLAINS PETROLEUM OPERATING COMPANY		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 415 W. WALL, SUITE 1000 MIDLAND, TX 79701		7. UNIT AGREEMENT NAME Bluitt San Andres Unit Sec.13
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit Letter H, 1980' FNL & 660' FEL		8. FARM OR LEASE NAME
14. PERMIT NO.		9. WELL NO. 8
15. ELEVATIONS (Show whether OF, RT, CR, etc.) 3995 GL		10. FIELD AND POOL, OR WILDCAT Bluitt San Andres Assoc.
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec.13, T8S, R37E
		12. COUNTY OR PARISH Roosevelt
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)


17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

In response to your letter dated Jan. 20, 1994, PPOC plans to plug and abandon this well and requests approval of the following plugging program.

1. Set plug across perfs 4670'-98' ¹⁸ (10 SX) 140' cmt. plug from PBD to 4607'. Tag plug.
2. Cut and recover approximately 3500' of 4-1/2" casing
3. Set 10 SX plug at TOC 130' cmt. plug centered on 4 1/2" stub. Tag plug
4. Set 10 SX plug at surface csg shoe @ 303' 26 SX, 100' centered on shoe (353'-453')
5. Set surface plug with marker Minimum 50' cmt. plug.

API No. 30-041-20175

* Additional plug: 120' cmt, 2200' - 2080'.



18. I hereby certify that the foregoing is true and correct

SIGNED

Bonnie Hubbard

TITLE

Administrative Assistant

DATE

Jan. 28, 1994

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

approved as modified

DATE

FEB 11 1994

*See Instructions on Reverse Side