

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K 3724	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name None
2. Name of Operator SAGE ENERGY COMPANY		8. Farm or Lease Name Cabot State
3. Address of Operator P. O. Drawer 3068, Midland, Texas 79702		9. Well No. 3
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>T-8-S</u> RANGE <u>R-36-E</u> NMPM.		10. Field and Pool, or Wildcat Vada Penn
15. Elevation. (Show whether DF, RT, GR, etc.) 4117' RKB		12. County Roosevelt

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set cast iron bridge plug with 35' cement at 9650±
Cut 5½" and pull as much as possible 5000±
Set 100' plug 1/2 in and 1/2 out at 5½" stub.
100' plug at Top of San Andres (3990')
100' plug at shoe of 8 5/8" 1/2 in and 1/2 out, unless top of San Andres is close to
8 5/8" shoe at 4050±; then 1 plug will be OK.
Cut 8 5/8" as low as possible 1200±.
100' at 8 5/8" stub.
100' at 13 3/8" shoe at 397'.
10 sxs surface and marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. L. Jones Helmy TITLE Production Clerk DATE March 18, 1986

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR TITLE _____ DATE MAR 21 1986

CONDITIONS OF APPROVAL, IF ANY: