Form approved, Pudget Bureau No. 42 R1424.
50 5 LEASE DESIGNATION AND SERIAL NO.

GEOLOGICAL S	URVEY HORRS, NEW MEXICO	NM 9033
SUNDRY NOTICES AND RECEIVED HER THE SUNDRY NOTICES AND RECEIVE HER TO SEE THE SUNDRY PERMIT	PORTS ON WELLS spen or plug back to a different reservoir.	NA NA
1.		7. UNIT AGREEMENT NAME
OIL XX GAS COTHER		
2. NAME OF OPERATOR		S. FARM OR LEASE NAME
Sage Energy Company		Bragg-Federal
3. ADDRESS OF OPERATOR		9. WELL NO.
P. O. Drawer 3068, Midland, Texas 79702 4. Towards of Well (Report location clearly and in accordance with any State requirements.* See this space 17 below.) At surface Unit E, 1830' from the North and 660' from the West Line of Section 28, T-8-S, R-36-E		1-Y
		Vada Pennsylvania
		11. SEC., T., R., M., OE BLE. AND SCRVEY OR AREA Sec. 28, T-8-S, R-36-E
	iow whether DF, Rf, GR, etc.)	12. COUNTY OR PARISH 13. STATE
4104'		Roosevelt New Mexico
Check Appropriate Box To	Indicate Nature of Notice, Report,	- · · · · · · · · · · · · · · · · · · ·
NOTICE OF INTENTION TO:	SU	BSEQUENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASIN	WATEE SHUT-OFF	REPAIRING WELL
FRACTURE TREAT MULTIPLE COMPLETS	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE : ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT* XX
(Other)	(Other)(Note: Report re	sults of multiple completion on Well completion Report and Log form.)
pull. 4-25-84 Spot 20 sxs plug at 4650 across 5½" csg. stub. ta 4-27-85 Shot 8 5/8" csg. off at 4-29-85 Spot 80 sxs plug at 460"	of retainer, shot 5½" csg.	off at 4598; could not off at 4330, spot 40 sxs plug ag at 8 5/8; shoe at 4140; oss 8 5/8; csg stub.
18. I hereby certify that the foregoing is true and correct SIGNED Frances Fieldy grad (This space for Federal or State office use) APPROVED BY	TITLE Production Clerk	DATE April 30, 1985 APPROVED
CONDITIONS OF APPROVAL, IF ANY:	TITLE	PETER W CHESTER

*See Instructions on Reverse Side

JAN 30 1987

BUREAU OF LAND MANAGEMENT ROSWELL RESOURCE AREA